## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

## P. O. BOX 2088 SANTA FE, NEW MEXICO 87501

Form C-102 Revised 10-1-1

All distances must be from the outer boundaries of the Section. Operator Lease Well No. Gary-Williams Oil Producer, Inc. Penistaia 11 1 Unit Letter Section Township County Α 11 20N Sandoval Actual Footage Location of Well: feet from the North West Ground Level Elev. Producing Formation Dedicated Acreage: 6949 Mancos Rio Puerco N - 320Acres 1. Outline the acreage dedicated to the subject well by colored pencil or hachure marks on the plat below. 2. If more than one lease is dedicated to the well, outline each and identify the ownership thereof (both as to working interest and royalty). 3. If more than one lease of different ownership is dedicated to the well, have the interests of all owners been consolidated by communitization, unitization, force-pooling. etc? Yes □ No If answer is "yes," type of consolidation \_ If answer is "no," list the owners and tract descriptions which have actually been consolidated. (Use reverse side of this form if necessary.)\_ No allowable will be assigned to the well until all interests have been consolidated (by communitization, unitization, forced-pooling, or otherwise) or until a non-standard unit, eliminating such interests, has been approved by the Division CERTIFICATION I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief. Name W.P. Marx Position Operations Manager Company Gary-Williams Oil Producer 8/16/85 I hereby certify that the well location shown on this plat was platted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my Knowledge and belief. Please see original plat Date Surveyed Registered Professional Engineer and/or Land Surveyor Certificate No. 330 660 1320 1650 1980 2310 2000 1500 1000 500