Budget Bureau No. 1004-0135 UNITED STATES

SUBMIT IN TRIPLICATE®

(Other instructions on rerespectively) Expires August 31, 1985 Form 3160-5 (November 1983) 5. LEASE DESIGNATION AND SERIAL NO. (Form rly 9-331) BUREAU OF LAND MANAGEMENT NM-36936 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.) N/A 7. UNIT AGREEMENT NAME N/A GAS Will WELL | OTHER 8. FARM OR LEASE NAME NAME OF OPERATOR San Isidro 15 The Gary-Williams Company (Formerly Gary-Williams Oil Producer) 9. WBLL NO. 4 115 Inverness Drive East, Englewood, CO 80112-5116 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.) 10. FIELD AND POOL, OR WILDCAT Rio Puerco Mancos 11. SHC., T., R., M., OR BLK. AND SURVEY OR AREA 660' FNL & 990' FWL (NW NW) Section 15-T20N-R3W NW NW 15-T20N-R3W 12. COUNTY OR PARISH | 13. STATE 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO. 6855' GR NM Sandoval Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data 16 SUBSCOUDIT REPORT OF: NOTICE OF INTENTION TO: REPAIRING WELL WATER SHUT-OFF PULL OR ALTER CASING TEST WATER SHUT-OFF ALTERING CASING MULTIPLE COMPLETE PRACTURE TREATMENT FRACTURE TREAT SHOOTING OR ACIDIZING ARANDON MENT ABANDON* SHOOT OR ACIDIZE REPAIR WELL CHANGE PLANS (Nors: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) Request Long-Term Shut-In 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.) The Gary-Williams Company respectfully requests permission for long term shut in status for the above mentioned well. Current depressed oil prices make this marginal well uneconomical to produce. In the absence of an approved suspension of production, there may be a premature abandonment of the well and resulting loss of recoverable reserves. Rece: 6/8/89 19. I hereby comity that the foregoing is true and correct TITLE Compliance Administrator 5/23/89 SIGNED Nancy Menonald DATE __ (This space for Federal or State office use) JUN 06 1989 APEA MANAGER APPROVED BY (ORIG. SGD.) JOHN M. ANDREWS, JR. TITLE RIO PUERCO RESOURCE AREA

*See: Instructions on Reverse Side

THIS APPROVAL EXPIRES MAY 31, 1990.