5. LEASE

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

0.501.0010.11	NUU-L-14-20-5356
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	Navajo Allotted
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil 🗔 gas 🖂	Dome_Tesoro 22
well well other	9. WELL NO.
2. NAME OF OPERATOR	4
DOME PETROLEUM CORP.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR 501 Airport Dr., Suite#	Undesignated Gallup
114, Farmington, New Mexico 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	ARE <b>A</b>
below.)	Sec. 22, T22N, R7W
AT SURFACE: 850' FNL, 1700' FWL AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH:	Sandoval New Mexico
16 CHECK APPROPRIATE BOX TO INDICATE NATURE OF MARKET	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	6865' GR
TEST WATER SHUT-OFF	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
FRACTURE TREAT	
SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zone
MULTIPLE COMPLETE	change on Form 9–330.)
CHANGE ZONES 🗍 🛗	
ABANDON*	
(other) Spud & Set Surface Casing	
- <del></del>	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinent	rectionally drilled, give subsurface locations and to this work.)*
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di	rectionally drilled, give subsurface locations and to this work.)*  Industry to the to the term of the
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinent Spudded 12½" hole at 4:00 a.m., 2/21/81. Drille 8 5/8", 24#, J-55, ST&C casing. Casing landed a Class "B" with 6% CaCl & 2% Floseal/sx. Plug do	rectionally drilled, give subsurface locations and to this work.)*  Indicate to 250'. Ran 5 jts. (229') of the 243' K.B. Cemented with 200 solution at 2:30 p.m., 2/21/81.
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinent Spudded 12¼" hole at 4:00 a.m., 2/21/81. Drille 8 5/8", 24#, J-55, ST&C casing. Casing landed a Class "B" with 6% CaCl & 2% Floseal/sx. Plug do	rectionally drilled, give subsurface locations and to this work.)*  ed to 250'. Ran 5 jts. (229') of it 243' K.B. Cemented with 200 s wn at 2:30 p.m., 2/21/81.
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinent.  Spudded 12¼" hole at 4:00 a.m., 2/21/81. Drille 8 5/8", 24#, J-55, ST&C casing. Casing landed a Class "B" with 6% CaCl & 2% Floseal/sx. Plug do Circulated Cement.	rectionally drilled, give subsurface locations and to this work.)*  Industry to the desired to the desired to 250'. Ran 5 jts. (229') of the 243' K.B. Cemented with 200 sown at 2:30 p.m., 2/21/81.
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinent.  Spudded 12½" hole at 4:00 a.m., 2/21/81. Drille 8 5/8", 24#, J-55, ST&C casing. Casing landed a Class "B" with 6% CaCl & 2% Floseal/sx. Plug do Circulated Cement.	rectionally drilled, give subsurface locations and to this work.)*  Indicate the description of the term of the te
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinent.  Spudded 12½" hole at 4:00 a.m., 2/21/81. Drille 8 5/8", 24#, J-55, ST&C casing. Casing landed a Class "B" with 6% CaCl & 2% Floseal/sx. Plug do Circulated Cement.  Subsurface Safety Valve: Manu. and Type  18. Thereby certify that the foregoing is true and correct	rectionally drilled, give subsurface locations and to this work.)*  Indicate the description of the term of the te
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is displayed and true vertical depths for all markers and zones pertinent.  Spudded 12½" hole at 4:00 a.m., 2/21/81. Drille 8 5/8", 24#, J-55, ST&C casing. Casing landed a Class "B" with 6% CaCl & 2% Floseal/sx. Plug do Circulated Cement.  Subsurface Safety Valve: Manu. and Type  18. Thereby certify that the foregoing is true and correct and correct are also as a	rectionally drilled, give subsurface locations and to this work.)*  Indicate the description of the term of the te
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is display measured and true vertical depths for all markers and zones pertinent.  Spudded 12½" hole at 4:00 a.m., 2/21/81. Drille 8 5/8", 24#, J-55, ST&C casing. Casing landed a Class "B" with 6% CaCl & 2% Floseal/sx. Plug do Circulated Cement.  Subsurface Safety Valve: Manu. and Type  18. Thereby certify that the foregoing is true and correct signed fazer.  Signed James Hazer.  TITLE Drlq.&Prod.Foregoing Casing Strue and Correct Signed Title Drlq.&Prod.Foregoing Strue and Correct Signed States Title Drlq.&Prod.Foregoing Strue States S	rectionally drilled, give subsurface locations and to this work.)*  Indicate the description of the term of the te

u-ph

\*See Instructions on Reverse Side