	5-51-57	UNITED STATI	ES	SUBMIT IN TRIPLICAL (Other instructions on verse side)	TE*	Form appr Budget Bu 5. LEASE DESIGNATION	reau No. 42-R1424.
				( verse side)		Contract N	
	·	GEOLOGICAL SU			-	6. IF INDIAN, ALLOT	TEE OR TRIBE NAME
(Do not use thi	S form for propuse "APPLIC	TICES AND REP cosals to drill or to deep cation for permit—	ORTS ON en or plug back for such propos	WELLS to a different reservoir. als.)		Jicarilla	Apache
OIL GAS WELL						7. UNIT AGREEMENT	NAME
NAME OF OPERATOR	U OTHER					8. FARM OR LEASE N	
JACK A. CO	OLE			The state of the s		Indian Be	end
ADDRESS OF OPERATO			1			9. WELL NO.	
P. O. Box		Farmington,					
See also space 17 be	Report location low.)	clearly and in accordance		e requirements.	-	10. FIELD AND POOL,	ctured Clif:
At surface	120'FNL,	1120'FWL		OLOGICA, SHAVEY	-	11. SEC., T., R., M., O SURVEY OR AR Sec. 25-T2	R BLK. AND
4. PERMIT NO.		7386 GL	w whether DF, RT,	GR. etc.)		12. COUNTY OF PARI	N.M.
		1300 GL				Dandoval	11111
8.	Check A	appropriate Box To I	Indicate Natu	re of Notice, Report,	or Ot	her Data	
	NOTICE OF INTE	ENTION TO:	1	<b>8</b> U	BSEQUE	NT REPORT OF:	
TEST WATER SHUT-	-OFF	PULL OR ALTER CASING		WATER SHUT-OFF	X	REPAIRIN	G WELL
FRACTURE TREAT		MULTIPLE COMPLETE		FRACTURE TREATMENT		ALTERING	CASING
SHOOT OR ACIDIZE		ABANDON*		SHOOTING OR ACIDIZING		ABANDON	MENT*
REPAIR WELL		CHANGE PLANS		(Other)		#	
(Other)				Completion or Re-	complet	f multiple completion tion Report and Log	form.)
7. DESCRIBE PROPOSED proposed work. nent to this work.	or completed of If well is direct ) *	PERATIONS (Clearly state tionally drilled, give sub	all pertinent de surface locations	tails, and give pertinent ( and measured and true v	lates, i ertical	ncluding estimated ( depths for all mark	date of starting any ters and zones perti-
7. DESCRIBE PROPOSED proposed work. nent to this work.  7/14/81	T.D. 3	208'	2", 10.50	tails, and give pertinent of and measured and true v			
nent to this work.	T.D. 3 Ran 74 set at 100 sac	208' joints 4-1/2 3147.97' wit	2", 10.50 h: emix (2%		55 c	casing (31	47.17')
nent to this work.	T.D. 3 Ran 74 set at 100 sac	208' joints 4-1/2 3147.97' wit	2", 10.50 h: emix (2%	% 11.60, K-	55 c	casing (31	47.17') onite
7/14/81	T.D. 3 Ran 74 set at  100 sac per sac	208' joints 4-1/2 3147.97' wit ks 50-50 Poz k. Calculat	2", 10.50 h: emix (2%	% 11.60, K-	55 c	casing (31	47.17') onite
FOR: JAC	T.D. 3 Ran 74 set at  100 sac per sac	208' joints 4-1/2 3147.97' wite ks 50-50 Poz k. Calculat	2", 10.50 ch: mix (2% ced top c	Gel) with 6-of cement 250	55 c	BLM FARM	47.17') onite
7/14/81	T.D. 3 Ran 74 set at  100 sac per sac  K A. COL	208' joints 4-1/2 3147.97' with the second s	2", 10.50 ch: mix (2% ced top o	% 11.60, K-	55 c	BLM FARM	47.17') onite

\*See Instructions on Reverse Side