1. oil well

D

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

other

3. ADDRESS OF OPERATOR P.O. Box 191 Farmington, N.M. 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17

810'FNL, 820'FEL

 \mathbf{x}

well

AT TOP PROD. INTERVAL:

2. NAME OF OPERATOR JACK A. COLE

AT SURFACE:

AT TOTAL DEPTH:

UNITED STATES	
DEPARTMENT OF THE INTERIOR	
GEOLOGICAL SURVEY	

	i Approved. et Bureau No. 42–R1424
5. LEASE Contract No. 5	55-A
6. IF INDIAN, ALLOTTER Jicarilla Apac	OR TRIBE NAME
7. UNIT AGREEMENT N	AME
8. FARM OR LEASE NAM Indian Bend	ME.
9. WELL NO. 8	<u> </u>
10. FIELD OR WILDCAT N Ballard Pictur	
11. SEC., T., R., M., OR I AREA	
Sec. 36-T23N-R	23W
12. COUNTY OR PARISH Sandoval	13. STATE N.M. 87401
l	

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

14. API NO. 30-043-20563

15. ELEVATIONS (SHOW DF, KDB, AND WD) 7269'G.L.

REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)

SUBSEQUENT REPORT OF: (NOTE: Report results of multiple completion or zone Tarah Maria Arah

change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

SEE ATTACHED FOR FRACTURE TREATMENT



Subsurface Safety Valve: Manu. and Type			Set @	Ft.
18. I hereby certify that the foregoing is true FOR: JACK A ORIGINAL SIGNED EWELL N. WELLIN. WALLSON,	and correct) BY President, Wal SH ^{TITLE} Engr. & Prod.		9/17/81	
(This space for Federal or State office use)				
APPROVED BY	TITLE	DATE	. <u> </u>	
			2 o 1981	

*See Instructions on Reverse Side

INGTO: Sma bY.

Formation Cliffs _ Stage	
Operator Jack A. cole	Lease and Well Indian Bend No.
Correlation Log	Type Gamma Ray From 2400 To 2913
Temporary Bridge Plug	Type None Set At
Perforations	2866'-2880', 14 feet 20 holes - Per foot type 3 1/8" Bull Jet
Foam Frac	
Pad - Foam	gallons. Additives 2% Kcl.
Foam	45,000 gallons. Additives 2% Kcl.
•	
Sand	84,000 lbs. Size 10-20
Flush - Foam	2,100 gallons. Additives 2% Kcl.
Breakdown	psig
Ave. Treating Pressure	psig
Max. Treating Pressure	psig
Ave. Injecton Rate	20.0 BPM
Hydraulic Horsepower	196 HHP Nitrogen 456,400 SCF
Instantaneous SIP -	psig
5 Minute SIP	psig SEP 23 1981
10 Minute SIP	1140 psig OIL CON. COM. DIST. 3
15 Minute SIP	1100 psig
Ball Drops:	None Balls at gallons psig
	incr Balls at gallons psig
e.	incr Balls at gallons psig incr
Remarks: Ball off with 30	Rubber Balls in 1000 gallons 7 1/2% Hcl.
	- Walsh ENGINEERING & PRODUCTION COR