

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different formation.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

NM-16579

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

N/A

7. UNIT AGREEMENT NAME

N/A

8. FARM OR LEASE NAME

Taylor 30

9. WELL NO.

15

10. FIELD AND POOL, OR WILDCAT

Rio Puerco Mancos

11. SEC., T., R., N., OR S.E. AND  
SURVEY OR AREA

SW SW 30-T21N-R3W

12. COUNTY OR PARISH

Sandoval

13. STATE

NM

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

JUN 03 1987

2. NAME OF OPERATOR

Gary-Williams Oil Producer, Inc.

BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA

3. ADDRESS OF OPERATOR

115 Inverness Drive East, Englewood, CO 80112-5116

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

990' FSL & 1200' FWL (SW SW) Section 30-T21N-R3W

14. PERMIT NO.

15. ELEVATIONS (Show whether SP, ST, GR, etc.)

7077' GR

12. COUNTY OR PARISH

Sandoval

13. STATE

NM

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) Request Long Term Shut In ☒

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

☐  
☐  
☐  
☐  
☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☐

☐  
☐  
☐  
☐  
☐

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Gary-Williams Oil Producer, Inc. respectfully requests permission to continue the suspension of production on the above mentioned well. Current depressed oil prices make this marginal well uneconomical to produce.

There are no known problems with the casing integrity due to the fact that the cement was circulated to surface and the casing is less than 5 years old. Because of the existing condition of the well, GWOP requests that the testing requirements be waived at this time.

In the absence of an approved suspension, there may be a premature abandonment of the well and resulting loss of recoverable reserves.

RECEIVED  
JUN - 9 1987  
OIL CON. DIV.  
BOL 2

Approved Until 5/31/88

18. I hereby certify that the foregoing is true and correct

SIGNED

Nancy McDonald

TITLE Compliance Administrator

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

DATE 5/29/87

JUN 05 1987

from A. Inchausti

\*See Instructions on Reverse Side