Budget Bureau No. 1004-0135 UNITED STATES

BUBMIT IN TRIPLICATE*

Other Instructions on reverse side) Form 3160-5 (Navember 1983) Expires August 31, 1985 5. ELBE DESIGNATION AND SERIAL NO. (Formerly 9-331) NMA 17749 BUREAU OF LAND MANAGEMENT 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT" for such proposals.) 7. UNIT AGREEMENT NAME WELL Wildcat OTHER WELL. R. PARM OR LEADE NAME 2. NAME OF OPERATOR Shirl Enexco, Inc WHILL BO. 3. ADDRESS OF OPERATOR LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface 10. FIELD AND POOL, OR WILDCAT RECEIVED Wildcat 11. SEC., T., R., M., OR BLE. AND SURVEY OR ARMA 990' FNL 990' FEC JUL 2 41984 Sec. 9 16N-2W 15. BLEVATIONS (Show whether D. HT. OF TELL) COLUNCE AREA. 12. COUNTY OR PARISH | 13. STATE 14. PERMIT NO. Sandavol New Mexico 6245 GL 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT EMPORT OF: REPAIRING WELL PULL OR ALTER CASING WATER SHUT-OFF TEST WATER SHUT-OFF ALTERING CASING FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT ABANDON* SHOOTING OR ACIDIZING ABANDON MENT SHOOT OR ACIDIZE

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.)*

Intent - 5½" Casing

REPAIR WELL

(Other)

Set 100' plug at bottom

* See Attached

50' plug to surface

CHANGE PLANS

Set dry hole marker

JUL2 71984

CON. DIV.

ST. 3

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

		APPROVED	
18. I hereby certify that the foregoing is true and SIGNED full of 13 for	TITLE President	ASTAMEN 18/84	
(This space for Federal or State office use)		JUL 2 6 1984	
APPROVED BY	NMOCC	VS/J. Stan McKee AREA MANAGER	
o^ ~	*See Instructions on Reverse Side	FARMINGTON RESOURCE AREA	

United States Department of the Interior

BUREAU OF LAND MANAGEMENT Drawer 600 Farmington, New Mexico 87499

Attachment to Notice of ...

Intention to Abandon

		_
Re:	Permanent	Abandonmen

Well: | Shrrl

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."

 The Farmington Area Office (telephone (505) 325-4572) is to be notified in sufficient time for a representative to witness all plugging operations.

3. Blowout prevention equipment is required.

4. In addition to normal filling of pits and cleanup of location, additional surface restoration work may be required, i.e. ripping of pad and/or access road, reseeding, etc. We have asked the Surface Management Agency for the surface restoration requirements within 30 days. After plugging the well and before making final clean-up, you should contact this office unless you have already been advised as to what additional surface restoration work is required.

5. The following modifications to your plugging program are to be made (when applicable):

plug 2700' to 2600' (Entrada)

plug 1893' to 1793' (Morrison)

plug 1520' to 1420' (Oakota)

plug 1053' to 953' (Gallup)

plug 50' to

Surface

Office Hours: 7:30 A.M. to 4:15 P. M.