				Form approved.		
Form 3160-5	HAUTED CTATI	CC armeter	IN MOVEY VOLUME	Budget Bureau No. 1004-0135 Expires August 31, 1985		
(November 1983)	UNITED STATE		IN TRIPLICATE*			
(Formerly 9-331)	DEPARTMENT OF THE	INTERIOR verse alde))	5. LEASE DESIGNATION A	NE SERIAL NO.	
	BUREAU OF LAND MANA	AGEMENT		NM-69186		
	NDRY NOTICES AND REP s form for proposals to drill or to deepe Use "APPLICATION FOR PERMIT—"			6. IF INDIAN, ALLOTTEE	OR TRIBE NAME	
1.		-510	PH 2: 15	7. UNIT AGREEMENT NAM	t	
WELL GAS WELL	OTHER	FARMINGTON	~~-			
2. NAME OF OPERATOR		FARMINGTON	SOURCE AREA	8. FARM OR LEASE NAME		
OTH WELL SHELL OTHER FARMINGTON RESCURCE AR JNC Resources FARMINGTON, NEW MEXICO			HEXICO .	Anthony	2/10/11	
3. ADDRESS OF OPERATOR				9. WELL, NO.		
6506 S. Lewis Suite 162 Tulsa, OK 74136				#2		
 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 				10. FIELD AND POOL, OR WILDCAT		
				Wildcat		
990' FNL & 990' FEL Section 9, T16N., R2W.				11. SEC., T., E., M., OR BLK. AND BURYEY OR AREA		
				Sec. 9, T16N-R2W.		
14. PERMIT NO.	15. ELEVATIONS (Show	15. ELEVATIONS (Show whether DF, RT, GR, etc.)		12. COUNTY OR PARISH 13. STATE		
	·	6245' GL		Sandova1	NM	
1.	Check Appropriate Box To I	ndicate Nature of Noi	ice, Report, or O	ther Data		
	NOTICE OF INTENTION TO:	i	SUBBROUGHT SEPORT OF:			
CASA WATER SHUT-C	PULL OR ALTER CASING	WATEU 5	SHUT-OF:	EEPAIRING WE		

Filled the entire hole w/9.2# mud. Ran tubing 2700' and spotted 15 sx cmt. Displaced hole w/61 sx mud. Pulled tubing to 1900' & pumped 15 sx cmt. Displaced w/10.4 Bbls. mud. Pulled to 1550' pumped 15 sx cmt., displaced w/9 Bbls. of mud. Pulled to 1000'. Pumped 15 sx cmt. displaced w/5.21 Bbls. of mud. Pulled to 360' & pumped 15 sx displaced w/2 Bbls. of mud. Pulled to 60' & pumped 8 sx and circulated to surface. Placed Dry hole marker and cleaned up location.

ASCAIRA PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent definite and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and necessared and true vertical depths for all markers and zones pertinent to this work.)*

SHOOTING OF ACIDARIL'S

P & A

(NOTE: Report results of multiple completion on Completion or Econopiction Report and Log form.)

ABANDON 5

SHOOF OR ACIDIC

LEPSIT WELL

COTTON

DEG B 0 1987

OIL CON. DIV. Approved as to plugging of the met of Liability under bend is releised under surface restoration is completed.

18. I hereby certify that the foregoing is true and correct Agent TITLE _ (This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side