5 MMS. Emn

2 Wexpro

1 File

Form Approved.

Form 9–331	Celsius	Budget Bureau No. 42-R1424
	STATES F THE INTERIOR	5. LEASE NM 16046
_	AL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)		7. UNIT AGREEMENT NAME
		8. FARM OR LEASE NAME Sis
1. oil gas XX othe	er	9. WELL NO.
2. NAME OF OPERATOR DUGAN PRODUCTION	N CORP.	10. FIELD OR WILDCAT NAME Undesignated PC
3. ADDRESS OF OPERATOR P O Box 208, Farmington, NM 87401		11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17		7 AREA Sec 21 T21N R4W
below.) AT SURFACE: 790' FNL - 1850' FWL		12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:		Sandoval NM 1
AT TOTAL DEPTH:	WATER NATURE OF MOTICE	14. API NO. 日本語 日本語 15年2年 日本語 15年2年 日本語 15年2年 日本語 15年2年 日本語 15年2年 15年2日 15年2月 15年2日 15年2月 15年2日 15年2月 15年2日 15年2月 15年2日 15年21月 15年21月21日 15年21月21日 15年21月21日 15年21月21日 15年21月21日 15年21月21日 15年21月 15年21月 15年21
16. CHECK APPROPRIATE BOX I REPORT, OR OTHER DATA	O INDICATE NATURE OF NOTICE	15. ELEVATIONS (SHOW DF, KDB, AND WD) 7142' GL; RKB = GL
REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:	7142 02; 1110
TEST WATER SHUT-OFF FRACTURE TREAT	RECEIVI	
SHOOT OR ACIDIZE  REPAIR WELL	SEP 3 0 198	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
PULL OR ALTER CASING  MULTIPLE COMPLETE		
CHANGE ZONES	FARMINGTON, N.	M
ABANDON*	XX 2-7/8" cas	ing & cement; TD
17. DESCRIBE PROPOSED OR CO	OMPLETED OPERATIONS (Clearly starting any proposed work. If well is pths for all markers and zones pertine	tate all pertinent details, and give pertinent dates s directionally drilled, give subsurface locations and nent to this work.)*
9-28-82 T.I.H	. with drill pipe. Circ	. hole clean. Laid down drill:
pipe. casin	g. T.E. 1924.71' set at	., 6.5#, 8 Rd, EUE tubing for a 1924' GL. (TD 1940')
Cemen	ted with 100 sx 2% loden	se followed by 50 sx neat. (Total
slurr	y 267 cu.ft.) Good mud ment to surface. P.O.B.	returns while cementing. Trace
or ce	ment to surface.	(III)
	,	
	4	OIL GOS 1982
Subsurface Safety Valve: Manu, and	<i>1</i> i	Die OM
18. I hereby certify that the foreg	oilighs true and correct	Engineer 9-29-82
SIGNED Thoma	MUALUTITLE Petroleum 5 A. Dugan	
	(This space for Federal or State	
APPROVED BY		DATECORPTED FUR RECORL

\*See Instructions on Reverse Side

BY \_\_\_