√orm.	3160	1-5
(Nove	mber	1983)
(Pam	erly	9 - 331)

## **JUNITED STATES**

SUBMIT IN TRIPLICATES

norm approved. Budget Bureau No. 1004-0135

Exp.	ires	August	31,	1985	
LEASE	DESI	GNATION	AND	MESSIAL	N.C

November 1983) Pormerly 9-331)  DEPARTMENT OF THE INTERIOR (Other instructions on recommendation)  BUREAU OF LAND MANAGEMENT			5. LEASE DESIGNATION AND HEATAL RC. NM-38576		
CHNIDDA	NOTICES AND REPORTS for proposals to drill or to deepen or pl "APPLICATION FOR PERMIT—" for su	S ON WELLS	6. IF INDIAN, ALLOTTEE N/A	OR TRIBE NAME	
OIL GAS		87 Ma - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 -	7. UNIT AGREEMENT NA	М±	
2. NAME OF OPERATOR	OTHER	- 41 9:34	8. FARM OR LEASE NAM	E	
Gary-Williams Oil	Producer Inc	SAMMOTOU DEPARTS -	San Isidro 1	.8	
3. ADDRESS OF OPERATOR	Troducer, The.	TARMINGTON SEW MENTION	9. WELL NO.		
115 Inverness Driv	ve East, Englewood, CO	80112-5116	8		
4. LOCATION OF WELL (Report See also space 17 below.)	location clearly and in accordance with	any State requirements.	10. FIELD AND POOL, OF		
At surface			Rio Puerco Mancos 11. sac., T., B., M., OR BLK. AND		
2015' FNL and 695'	' FEL (SE NE) Section 18	3-T2ON-R3W	SURVEY OR AREA		
			SE NE 18-T20	IN-R3W	
14. FERMIT NO.	15. BLEVATIONS (Show wheth	er DF, RT, GR, etc.)	12. COUNTY OR PARISH		
A. I BROWLE NO.	6852' KB		Sandoval	NM	
16.	heck Appropriate Box To Indica	se Nature of Notice Report or C	Other Data		
	OF INTENTION TO:		UBNT REPORT OF:		
NOTICE			REPAIRING V	WELL.	
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF FRACTURE TREATMENT	ALTERING CA		
FRACTURE TREAT	MULTIPLE COMPLETE	SHOOTING OR ACIDIZING	ABANDONME	NT*	
SHOOT OR ACIDIZE  REPAIR WELL	CHANGE PLANS	(Other)			
· · · · · · · · · · · · · · · · · · ·	g Term Shut In Status	(Norr - Report results	s of multiple completion eletion Report and Log for	on Well rm.)	
Gary-William	es Oil Producer, Inc. ("Cshut in status for the assurance shut in the status for the stat	GWOP") respectfully requ	AUG 0 6 198 Oil. CON. D	VED 7	
would be req	uired to return this we not justify payout on	ll to production. Curre	ent production a	and	
cement was c Because of t	known problems with the irculated to surface and he existing condition of the waved at this time.	d the casing is less tha	an 5 years old.		
	ce of an approved suspe and resulting loss of r		remature abando	nment	
		THIS APPROVAL	EXPIRES AUG	**************************************	
SHOWED MANLY A		Compliance Administrat	or date 7/	31/87	
(This space for Federal or	r State office use)				

TITLE \_

DATE .