

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM 37548	
2. NAME OF OPERATOR Champlin Petroleum Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR 420 Henry Ford Ave., Wilmington, California 90744		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface SESE (660' FSL and 660' FEL)		8. FARM OR LEASE NAME Federal 44-2	
14. PERMIT NO. Approved 4-17-84		9. WELL NO. #1	
15. ELEVATIONS (Show whether DF, ST, GL, etc.) 6926' GL, 6937' KB		10. FIELD AND POOL, OR WILDCAT Rio Puerco Mancos-Gallup	
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 2-T20N-R3W		12. COUNTY OR PARISH Sandoval	
13. STATE NM			

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PCLL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☒

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

NOTICE OF INTENT TO ABANDON

This tentative program was verbally approved by BLM Petroleum Engineer, Mr. Jim Lovato on 6-19-87.

Plug #1: Set CIBP at 4500', 50' above perforations. Spot a 50' lineal plug from 4500' to 4550' with 5 cf of Class "H" cement. Reverse hole with 9.2 ppg claybase mud. Freepoint, cut and retrieve 4-1/2" casing.

Plug #2: Spot a 100' lineal plug across 4-1/2" casing and cut w/25 cf of Class "H" cement.

Plug #3: Spot a 100' lineal plug across top of Cliffhouse formation @ 1905'-1805' w/25 cf of Class "H" cement.

Plug #4: Spot a 175' lineal plug across the entire Ojo Alamo formation at 845' to 670' w/ 40 cf of Class "H" cement.

Plug #5: Spot a 100' lineal plug across 9-5/8" casing shoe from 306'-206' w/25 cf of Class "H" cement.

Plug #6: Spot a 50' lineal surface plug w/11 cf of Class "H" cement. Cut casing 5' below GL and weld on plate with well information.

18. I hereby certify that the foregoing is true and correct

SIGNED P. M. McKinney

TITLE Petroleum Engineer

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

APPROVED 8/24/87

AS AMENDED

DATE AUG 24 1987

AUG 27 1987

OIL CON. DIV.
DIST. 3

AREA MANAGER

*See Instructions on Reverse Side

NMOCC

BUREAU OF LAND MANAGEMENT
CALLER SERVICE 4104
FARMINGTON, NEW MEXICO 87499

Attachement of Notice of
Intention to Abandon

Re: Permanent Abandonment

Well: 1 Federal 44-2

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."
2. The Farmington Office, telephone (505) 325-4572, is to be notified in sufficient time for a representative to witness all plugging operations.
3. Blowout prevention equipment is required.
4. The following modifications to your plugging program are to be made (when applicable):

- * 3) plug from 2645' - 2545' Mesaverde
- * 4) plug from 2013' - 1913' Chaco
- * 5) plug from 1124' - 615' Pictured Cliffs, Fruitland & Ojo Alamo
- * 7) Bradenhead Squeeze from Surface to 306'

Office Hours: 7:45 A.M. to 4:30 P.M.