

37. SUMMARY OF POROUS ZONES. (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

38.

GEOLOGIC MARKERS

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	TOP	
					MEAS. DEPTH	TRUE VERT. DEPTH
Ojo Alamo	675'	925'				
Kirtland-Fruitland	925'	1150'				
Pictured Cliffs	1150'	1965'				
Cliff House	1965'	2665'				
Menefee	2665'	3410'				
Point Lookout	3410'	3620'				
Mancos	3620'	4330'				
Gallup	4330'					