

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to surface.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

MAY 19 1986

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. NAME OF OPERATOR Gary-Williams Oil Producer, Inc.
3. ADDRESS OF OPERATOR 115 Inverness Drive East, Englewood, CO 80112-5116	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1650' FNL and 1980' FEL (SW NE) Section 15-T20N-R3W
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, ST, GR, etc.) 6835' GR

5. LEASE DESIGNATION AND SERIAL NO. NM-36936
6. IF INDIAN, ALLOTTEE OR TRIBE NAME N/A
7. UNIT AGREEMENT NAME N/A
8. FARM OR LEASE NAME San Isidro 15
9. WELL NO. 7
10. FIELD AND POOL, OR WILDCAT Rio Puerco Mancos
11. SEC., T., R., N., OR BLK. AND SURVEY OR AREA SW NE 15-T20N-R3W
12. COUNTY OR PARISH Sandoval
13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

(Other) Request to temporarily SI well ☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. USE HERE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and completion to this work.)*

Gary-Williams Oil Producer, Inc. respectfully requests approval to temporarily shut in the San Isidro 15, #7 well for an indefinite time period. Current depressed oil prices make this marginal well uneconomical to produce.

In January, 1986, production averaged 1.5 BOPD. The San Isidro 15, #7 was shut in during February and March 1986.

Approval for temporary shut in status for this well would prevent premature abandonment of significant recoverable hydrocarbon reserves.

RECEIVED

JUN 02 1986

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

RECEIVED
JUN 12 1986
OIL CON. DIV.
DIST. 9

6-12-87

18. I hereby certify that the foregoing is true and correct

SIGNED

W. D. Marx

TITLE Operations Manager

DATE

5/12/86

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED
AS AMENDED

DATE

JUN 12 1986

John S. Keller
AREA MANAGER

*See Instructions on Reverse Side

NMOCC