## P. O. BOX 2088 SANTA FE, NEW MEXICO 87501

Form C-102 Revised 10-1-7

All distances must be from the outer houndaries of the Section Well No. Lease Operator Gary-Williams Oil Producer, Inc. San Isidro 26 Unit Letter Section Township Range County 26 20N 3W Sandoval Actual Fastage Location of Well: 1900 2250 feet from the East feet from the North line and Dedicated Acreoge: Ground Level Elev. Producing Formation 6984' Undesignated Mesaverde Acre: 1. Outline the acreage dedicated to the subject well by colored pencil or hachure marks on the plat below. 2. If more than one lease is dedicated to the well, outline each and identify the ownership thereof (both as to working interest and royalty). 3. If more than one lease of different ownership is dedicated to the well, have the interests of all owners been consolidated by communitization, unitization, force-pooling. etc? If answer is "yes," type of consolidation \_\_\_ If answer is "no," list the owners and tract descriptions which have actually been consolidated. (Use reverse side of this form if necessary.). No allowable will be assigned to the well until all interests have been consolidated (by communitization, unitization. forced-pooling, or otherwise) or until a non-standard unit, climinating such interests, has been approved by the Division CERTIFICATION I hereby certify that the information contoined herein is true and complete to the best of my knowledge and belief. F.E. Farnham Vice Pres. of Prod & Dev £150° Gary-Williams Oil Producer, Ir. Date 2/14/86 I hereby certify that the well location shown on this plat was platted from field notes of actual surveys made by me or under my supervision, and that the same true and correct to the best of my knowledge and belief. See Original Surveyors Plat Date Surveyed Registered Professional Engineer and/or Land Surveyor Certificate No.