

DEPARTMENT OF THE INTERIOR (Precedence)
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. LEASE IDENTIFICATION AND SERIAL NO.
NM-24442
2. IF INDIAN, ALLOTTEE OR TRUST NAME
3. UNIT ASSIGNMENT NAME
4. FARM OR LEASE NAME
Federal 41-20
5. WELL NO.
1
6. FIELD AND POOL, OR WILDCAT
Wildcat
7. SEC., T., R., M., OR BLM. AND
SUBST. OR AREA

8. NAME OF OPERATOR
Champlin Petroleum Company

9. ADDRESS OF OPERATOR

10. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface NE NE NE (490' FNL & 420' FEL)

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

11. PERMIT NO.

12. ELEVATIONS (Show whether OF, BT, OR, etc.)

Approved 3-22-85

6572' GR, 6584' KB

Section 20, T18N-R3W

13. COUNTY OR PARISH 14. STATE

Sandoval N. Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOTING OR ACIDIZING
REPAIR WELL
(Other)

PULL OR ALTER CASING
MULTIPLE COMPLETION
ABANDON
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

REPAIRING WELL
ALTERING CASING
ABANDONMENT

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

15. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and tubes pertinent to this work.)

Plug and abandon well as follows:

Mix 80 bbls. mud (Vis= 36 sec), displace downhole, mix 60 bbls. mud (Vis = 36 sec) for plug displacement.

Set Plug #1 2080-1980' w/15 sx Class "B" w/2% CaCl₂. Displace w/mud. Cut off 4 1/2" casing @ 1450' KB.

Set Plug #2 1500-1400' w/ 15 sx Class "B" w/2% CaCl₂. Displace w/mud.

Set Plug #3 1325-1225' w/20 sx Class "B" w/2% CaCl₂. Displace w/mud.

Set Plug #4 190-90' w/20 sx Class "B" w/2% CaCl₂. Displace w/mud.

Set Plug #5 50'-0 w/10 sx Class "B" w/2% CaCl₂. Displace w/mud.

Cut off Bradenhead, cut off 7" casing. Put 10 sx cement in cellar. Weld steel plate on 9-5/8" casing.

Erect dry hole marker.

Permission to Plug and Abandon received from Earl Beecher-BLM and Frank Chavez-State of New Mexico.

16. I hereby certify that the foregoing is true and correct

SIGNED Ramona J. Rhoden TITLE Sr. Engineering Aide

DATE 4-22-85

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APR 29 1985

OIL CON. DIV.

*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.