Form Approved.

Budget Bureau No. 42–R1424

UNITED STATES

_		 	Pr	· co		~ ·		
	LEASE	 - C1 - 25	- 73	Ξ.		7.	3 13	
•				~:	·	/ iin		J

UNITED STATES	5. LEASE SF \$27081160-F							
DEPARTMENT OF THE INTERIOR	6. IF INDIAN, ALLOTTEE OR TRIBE NAME							
GEOLOGICAL SURVEY	6. If INDIAN, ALLOWED ON THIS PARTY							
THE PERSON WELLS	7. UNIT AGREEMENT NAME							
SUNDRY NOTICES AND REPORTS ON WELLS								
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME							
reservoir, use rothin 3-352 or is to the party of the control of t	SAN LUIS FEBERAL							
1. oil gas other	9. WELL NO.							
Well — Well	TORREON 18							
2. NAME OF OPERATOR	10. FIELD OR WILDCAT NAME							
NOEL REYNOLDS	MESA VERDE 11. SEC., T., R., M., OR BLK. AND SURVEY OR							
3. ADDRESS OF OPERATOR								
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	"I ADEA							
4. LOCATION OF WELL (REPORT ECCATION GLEARET, GG Space 1)	J 21-18 N 3W							
below.) AT SURFACE: 1810 F51 AND 1010 FEL	12. COUNTY OR PARISH 13. STATE							
AT TOP PROD. INTERVAL:	SANDIVAL AM							
AT TOTAL DEPTH: 6 45	14. API NO. 9, 4 4 8 3 5 € 8 9							
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,								
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)							
, DEPORT OF	6689 GR							
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	5 1 a d a d a d a d a d a d a d a d a d a							
TEST WATER SHUT-OFF	- Segia A である。							
FRACTURE TREAT SHOOT OR ACIDIZE								
REPAIR WELL	(NOTE: Report results of multiple completion or zone							
PULL OR ALTER CASING	change on Form 9–330.)							
MULTIPLE COMPLETE	Roddinick Roddin							
CHANGE ZONES								
ABANDON*	그							
(other) COMPLETE								
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates,								
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state an pertinent definition of the state of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* PROPOSE TO START COMPLETION PUMP NILL RUN TUBING Y RODS PLITON PUMP WILL RUN TUBING Y RODS PLITON								
measured and true territoria.	3-4 7-15:88 B B B B B B B B B B B B B B B B B B							
PRODUCE TO START COMPLETION	/							
TREPESE TO STATE PLIT	ON PHANTS THE BUTCH							
MILL RUN TUBING THE	그 그 그 그 전략하는 그 가는 그 없었다.							
Labora								
	그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그							
6 🖫 👊 iii) k i	DELVENIE E E							
9 I K								
	ng in the second of the second							
								
E T EE OIL C	ON. DIV EVERY DE REPL							
OIL OF COMPANY OF COMP	vst. 3 📑 i i i i i i i i i i i i i i i i i i							
© Eα Solo () Value Many and Type	Set @							
Subsurface Safety Valve: Manu. and Type								
18. I hereby certify that the foregoing is true and correct	· · · · · · · · · · · · · · · · · · ·							
SIGNED Man Roy-nolds TITLE OPERATOI	Q DATE 6-27-88							
(This space for Federal or State	office use)							
ADDROVED BY	DATE							
APPROVED BY	2 4 5 2 U L 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1							