

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-043-20831
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-1399
7. Lease Name or Unit Agreement Name Gus YJ State
8. Well No. 1
9. Pool name or Wildcat Lybrook-Gallup Ext.
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 7245' GR

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210

4. Well Location Unit Letter B : 660 Feet From The North Line and 1980 Feet From The East Line Section 32 Township 23N Range 6W NMPM Sandoval County
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Perforate, Acidize, Frac well <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-30-89. Drilled out DV tool at 4698'. Perforated 5429-5637' w/28 - .40" holes as follows: 5429, 30, 34, 35, 36, 5545, 46, 48, 49, 63, 64, 65, 5604, 05, 06, 07, 08, 09, 17, 18, 28, 29, 30, 31, 32, 35, 36 and 5637'. Acidized perms 5429-5637' in three stages w/2000 gals 7½% NEFE acid.

8-31-89. Frac'd perms 5429-5637' w/108000 gals gelled (20#) 2% KCL water and 180000# 20/40 sand. Perforated 5131-5263' w/20 - .40" holes as follows: 5131, 32, 33, 72, 73, 74, 75, 5214, 15, 16, 17, 18, 23, 24, 25, 26, 27, 59, 62, and 5263'. Acidized perms 5131-5263' w/2000 gals 7½% NEFE acid and ball sealers. Frac'd perms 5131-5263' w/60000 gal gelled (20#) 2% KCL water and 100000# 20/40 sand.

CONFIDENTIAL - TIGHT HOLE!

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 9-1-89

TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY Original Signed by FRANK T. CHAVEZ SUPERVISOR DISTRICT 3 DATE SEP 05 1989

CONDITIONS OF APPROVAL, IF ANY: