Submit 5 Copies
Appropriate District Office
DISTRICT 1
P.O. Box 1980, Hobbs, NM 88240

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION

P.O. Box 2088 Santa Fe, New Mexico 87504-2088 also a nome Change, give to pre jor ID3

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410

REQUEST FOR ALLOWAR	ILE AND AUTHORIZATION
TO TRANSPORT OIL	

and or							Well A	PI NO.		
Operator BANNON ENERGY INCORPORATED						30-	30-043-20845			
Adress								- 		
3934 FM 1960	West, S	te #	240 H	lousto		as 770 (Please explain				
eason(s) for Filing (Check proper box)	_	- :	T					from Fe	ederal	19-12
ew Well		_nange in	Transport Dry Gas	r-1		ybrook				
ecompletion	Oil Caringhand	 □	Condens		U 11	7.2.2.0011				
hange in Operator	Casinghead	<u> </u>	Conocus	-w						
change of operator give name d address of previous operator										
. DESCRIPTION OF WELL	AND LEAS	SE							1	No
ease Name		Well No.			ng Formation			f Lease Federal or Fee	1	ase No. 8360
Lybrook South		16	Lyb:	rook (Gallup				3107	0300
ocation	1075			9,	outh	1978		F	East	1:
Unit LetterJ	_ : <u>1975</u>		Feet Fro	m The	outh Line	and	Fec	et From The		Line
Section 19 Townshi	in 23N		Range	6W	, NM	ıpm. Sar	ndoval			County
Section 19 Townsh	ip 232		Range		1100					
I. DESIGNATION OF TRAN	NSPORTER	OF O	IL AND	NATUI	RAL GAS					
lame of Authorized Transporter of Oil	L X X	or Conder	asate [Vomere (Othe			copy of this for		
Giant Refining C								Rd., Sco		
lame of Authorized Transporter of Castin BANNON ENERGY	nghead Gas TNCORPO	REE	or Dry (Gas				copy of this for Te240 H		
							l When	2	<u> </u>	
	 -		I To	Bas	le one noticelle	/connected/				
f well produces oil or liquids,	Unit C	Sec. 19	Twp. 2 3 N	Rge.	Is gas actually YES	connected?	117	15/90		
f well produces oil or liquids, ive location of tanks.				<u>.l</u>	YES		117	15/90		
f well produces oil or liquids, ive location of tanks. This production is commingled with tha				<u>.l</u>	YES		117	15/90		
f well produces oil or liquids, ve location of tanks. this production is commingled with tha V. COMPLETION DATA	nt from any other	er lease of	pool, giv	<u>.l</u>	YES		111/	15/90 Plug Back	Same Res'v	Diff Res'v
f well produces oil or liquids, ive location of tanks. This production is commingled with tha	nt from any other	Oil Wel	r pool, giv	e comming	YES ling order numb	er:	11/	Piug Back	Same Res'v	Diff Res'v
f well produces oil or liquids, ive location of tanks. This production is commingled with tha V. COMPLETION DATA Designate Type of Completion Date Studded	n - (X)	Oil Wel	r pool, giv	e comming	YES ling order numb New Well X Total Depth	er:	11/	15/90	Same Res'v	Diff Res'v
f well produces oil or liquids, we location of tanks. This production is commingled with that V. COMPLETION DATA Designate Type of Completion Date Spudded 10/14/90	n - (X) Date Comp	Oil Well X	r pool, giv	e comming	New Well X Total Depth 5710	Workover	11/	Plug Back 1		Diff Res'v
f well produces oil or liquids, ive location of tanks. This production is commingled with that V. COMPLETION DATA Designate Type of Completion Date Spudded 10/14/90 Flevations (DF, RKB, RT, GR, etc.)	n - (X) Date Comp 11/7	Oil Well X	r pool, giv	e comming	YES ling order numb New Well X Total Depth	Workover	11/	Piug Back		Diff Res'v
f well produces oil or liquids, ive location of tanks. This production is commingled with that V. COMPLETION DATA Designate Type of Completion Date Spudded 10/14/90 Elevations (DF, RKB, RT, GR, etc.) 7015 GR	n - (X) Date Comp 11/7	Oil Well X	r pool, giv	e comming	New Well X Total Depth 5710 Top Oil/Gas	Workover	11/	Plug Back P.B.T.D. 5623 Tubing Depth 5534 Depth Casing	Shoe	Diff Res'v
f well produces oil or liquids, ive location of tanks. This production is commingled with that V. COMPLETION DATA Designate Type of Completion Date Spudded 10/14/90 Elevations (DF, RKB, RT, GR, etc.) 7015 GR	n - (X) Date Comp 11/7	Oil Well X	r pool, giv	e comming	New Well X Total Depth 5710 Top Oil/Gas	Workover	11/	Plug Back	Shoe	Diff Res'v
this produces oil or liquids, ve location of tanks. This production is commingled with that v. COMPLETION DATA Designate Type of Completion Date Spudded 10/14/90 Elevations (DF, RKB, RT, GR, etc.) 7015 GR Perforations	n - (X) Date Comp 11/7 Name of Pr Lybr	Oil Well X I. Ready (/ 90 roducing F	r pool, giv	e commingi	New Well X Total Depth 5710 Top Oil/Gas I	Workover	Deepen	Plug Back	Shoe	_i
f well produces oil or liquids, ive location of tanks. This production is commingled with that V. COMPLETION DATA Designate Type of Completion Date Spudded 10/14/90 Elevations (DF, RKB, RT, GR, etc.) 7015 GR Perforations 5425-5521	n - (X) Date Comp 11/7 Name of Pr Lybr	Oil Well X II. Ready t / 90 roducing F	r pool, giv	e comming Gas Well	New Well X Total Depth 5710 Top Oil/Gas I 5425	Workover Pay NG RECOR	Deepen Deepen	Plug Back	Shoe	_i
f well produces oil or liquids, live location of tanks. This production is commingled with that V. COMPLETION DATA Designate Type of Completion Date Spudded 10/14/90 Elevations (DF, RKB, RT, GR, etc.) 7015 GR Perforations 5425-5521 HOLE SIZE	n - (X) Date Comp 11/7 Name of Pr Lybr	Oil Well X II. Ready to 190 ook (UBING	r pool, giv	e comming Gas Well	New Well X Total Depth 5710 Top Oil/Gas I 5425	Workover Pay OR RECORDEPTH SET	Deepen Deepen	Plug Back P.B.T.D. 5623 Tubing Depth 5534 Depth Casing 5710 S.	Shoe	_i
If well produces oil or liquids, ive location of tanks. If this production is commingled with that V. COMPLETION DATA Designate Type of Completion Date Spudded 10/14/90 Elevations (DF, RKB, RT, GR, etc.) 7015 GR Perforations 5425-5521 HOLE SIZE 12 1/4	n - (X) Date Comp 11/7 Name of Pr Lybr T CAS 8 5	Oil Well X II. Ready to 190 ook (UBING SING & 7 / 8 / 2	r pool, giv	e comming Gas Well	New Well X Total Depth 5710 Top Oil/Gas I 5425 CEMENTI	Workover NG RECOF DEPTH SET	Deepen Deepen	Plug Back	Shoe ACKS CEN	_i
f well produces oil or liquids, ive location of tanks. It this production is commingled with that V. COMPLETION DATA Designate Type of Completion Date Spudded 10/14/90 Elevations (DF, RKB, RT, GR, etc.) 7015 GR Perforations 5425-5521 HOLE SIZE 12/4 7/8	n - (X) Date Comp 11/7 Name of Pr Lybr T CAS	Oil Well X II. Ready to 190 ook (UBING SING & 7 / 8 / 2	r pool, giv	e comming Gas Well	New Well X Total Depth 5710 Top Oil/Gas I 5425	Workover NG RECOF DEPTH SET	Deepen Deepen	Plug Back P.B.T.D. 5623 Tubing Depth 5534 Depth Casing 5710 S.	Shoe ACKS CEN	_i
If well produces oil or liquids, ive location of tanks. If this production is commingled with that V. COMPLETION DATA Designate Type of Completion Date Spudded 10/14/90 Elevations (DF, RKB, RT, GR, etc.) 7015 GR Perforations 5425-5521 HOLE SIZE 12 1/4 7 7/8 N/A	Date Comp 11/7 Name of Pr Ly br T CAS 8 5 4 1 2 3	Oil Well X II. Ready (/ 90 ook () UBING & 7 / 8 / 2 / 8	r pool, giv	e comming! Gas Well Top NG AND SIZE	New Well X Total Depth 5710 Top Oil/Gas I 5425 CEMENTI	Workover NG RECOF DEPTH SET	Deepen Deepen	Plug Back	Shoe ACKS CEN	_i
f well produces oil or liquids, ive location of tanks. This production is commingled with that V. COMPLETION DATA Designate Type of Completion Date Spudded 10/14/90 Elevations (DF, RKB, RT, GR, etc.) 7015 GR Perforations 5425-5521 HOLE SIZE 12 1/4 7 7/8 N/A V. TEST DATA AND REQUI	Date Comp 11/7 Date Comp 11/7 Name of Pr Lybr T CAS 8 5 4 1 2 3 EST FOR A	Oil Well X II. Ready to 1/90 Oducing Fook (UBING SING & 7/8 / 2 / 8	r pool, giv	e comming Gas Well TP NG AND SIZE	New Well X Total Depth 5710 Top Oil/Gas I 5425 CEMENTII	Workover NG RECOR DEPTH SET	Deepen	Plug Back	Shoe ACKS CEN	IENT
f well produces oil or liquids, live location of tanks. This production is commingled with that V. COMPLETION DATA Designate Type of Completion Date Spudded 10/14/90 Elevations (DF, RKB, RT, GR, etc.) 7015 GR Perforations 5425-5521 HOLE SIZE 12 1/4 7 7/8 N/A V. TEST DATA AND REQUICAL WELL (Test must be after	n - (X) Date Comp 11/7 Name of Pr Lybr T CAS 8 5 4 1 2 3 EST FOR A	Oil Well X I. Ready to 190 Ook Couring Fook Couring Foo	r pool, giv	e comming Gas Well TP NG AND SIZE	New Well X Total Depth 5710 Top Oil/Gas I 5425 CEMENTII 30 57.	Workover Pay DEPTH SET O 7 1 0 3 4	Deepen Deepen Downble for th	Plug Back P.B.T.D. P.B.T.D. F.S. P.B.T.D. P.B	Shoe ACKS CEN	IENT
f well produces oil or liquids, ive location of tanks. It this production is commingled with that V. COMPLETION DATA Designate Type of Completion Date Spudded 10/14/90 Elevations (DF, RKB, RT, GR, etc.) 7015 GR Perforations 5425-5521 HOLE SIZE 12 1/4 7 7/8 N/A V. TEST DATA AND REQUIPMENT OIL WELL (Test must be after	Date Comp 11/7 Date Comp 11/7 Name of Pr Lybr T CAS 8 5 4 1 2 3 EST FOR A	Oil Well X II. Ready to 1900 roducing Fook (1900) UBING SING & 7 / 8 LLOW total volumests	r pool, giv	e comming Gas Well TP NG AND SIZE	New Well X Total Depth 5710 Top Oil/Gas I 5425 CEMENTII 30 57. 553	Workover NG RECOR DEPTH SET	Deepen Deepen owable for th	Plug Back P.B.T.D.	Shoe ACKS CEN	IENT
ive location of tanks. It this production is commingled with that V. COMPLETION DATA Designate Type of Completion Date Spudded 10/14/90 Elevations (DF, RKB, RT, GR, etc.) 7015 GR Perforations 5425-5521 HOLE SIZE 12 1/4 7 7/8 N/A V. TEST DATA AND REQUITED OIL WELL (Test must be after Date First New Oil Run To Tank 11/7/90	Date Comp 11/7 Name of Pr Lybr T CAS 8 5 4 1 2 3 EST FOR A r recovery of to Date of Tet 11/7	Oil Well X II. Ready to 190 ook (190 oo	r pool, giv	e comming Gas Well TP NG AND SIZE	New Well X Total Depth 5710 Top Oil/Gas I 5425 CEMENTII 30 573 553 to be equal to or Producing M Plung Casing Press	NG RECORDEPTH SET	Deepen Deepen owable for th	Plug Back P.B.T.D.	Shoe ACKS CEM or full 24 ho	IENT
If well produces oil or liquids, give location of tanks. If this production is commingled with that IV. COMPLETION DATA Designate Type of Completion Date Spudded 10/14/90 Elevations (DF, RKB, RT, GR, etc.) 7015 GR Perforations 5425-5521 HOLE SIZE 12 1/4 7 7/8 N/A V. TEST DATA AND REQUIT OIL WELL (Test must be after Date First New Oil Run To Tank	T CAS 8 5 4 1 2 3 EST FOR A	Oil Well X II. Ready to 190 ook of 190 OUGHING SING & 7 / 8 / 2 / 8 LLOW Mad volume st 190	r pool, giv	e comming Gas Well TP NG AND SIZE	New Well X Total Depth 5710 Top Oil/Gas I 5425 CEMENTII 30 571 553 It be equal to or Producing M Plungs Casing Press 575	Workover Pay DEPTH SET Of Overline the service of the service	Deepen Deepen owable for th	Plug Back P.B.T.D. 56 2 3 Tubing Depth 55 3 4 Depth Casing 57 1 0 S 250 N/A is depth or be foreic.)	Shoe ACKS CEN or full 24 ho	IENT
If well produces oil or liquids, give location of tanks. If this production is commingled with that V. COMPLETION DATA Designate Type of Completion Date Spudded 10/14/90 Elevations (DF, RKB, RT, GR, etc.) 7015 GR Perforations 5425-5521 HOLE SIZE 12 1/4 7 7/8 N/A V. TEST DATA AND REQUIPMENT OIL WELL (Test must be after Date First New Oil Run To Tank 11/7/90 Length of Test	T CAS 8 5 4 1 2 3 EST FOR A r recovery of to Date from any other	Oil Well X II. Ready to 1/90 roducing Fook (1/90) CIBING & 7 1/8 1/2 1/8 LLOW Mal voluments 1/90 CESSURE	r pool, giv	e comming Gas Well TP NG AND SIZE	New Well X Total Depth 5710 Top Oil/Gas I 5425 CEMENTII 30 573 553 to be equal to or Producing M Plung Casing Press	Workover Pay DEPTH SET Of Overline the service of the service	Deepen Deepen Owable for the through, gas lift,	Plug Back P.B.T.D.	Shoe ACKS CEN or full 24 ho	IENT

Casing Pressure (Shut-in)

Tubing Pressure (Shut-in)

lesting Method (pilot, back pr.)