(November 1983) (Formerly 9-331)	DEPART BUREA	MENT OF THE IN	SUBMIT IN TRIPLICA TERIOR (Other instructions on verse side) EMENT	5. LEASE DESIGNATE	BU No. 1004-0135 2St 31, 1985 ON AND MEIAL NO.	
	UNDRY NOT	ICES AND REPORT ATION FOR PERMIT—" for	RTS ON WELES EIVED plug back to a different reservoir.	NM-6682 6. IF INDIAN, ALLOT	THE OR TRIBE NAME	
OIL XX GAI	LL OTHER		92 DEC 25 PM 0. 6	7. UNIT AGREEMENT	NAME	
2. NAME OF OPERAT	- -		919 FARMINGE	8. FARM OR LEASE N	IAMP	
BCO, INC. BCO OPERATOR BCO, INC. 3. ADDRESS OF OPERATOR				Y Federal B	Federal B	
135 Grant	9. WELL NO.					
4. LOCATION OF WELL See also space 17	14					
At surface		10. FIELD AND POOL, OR WILDCAT				
115	Lybrook G	Lybrook Gallup				
		SURVEY OR ARI	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA			
14. PERMIT NO.		SEC 27 T23N	D7W NMDM			
		I	S (Show whether DF, RT, GR, etc.)		SEC 27 T23N R7W NMPM 12. COUNTY OR PARISH 13. STATE	
		GL: 7276'		Sandova1	New Mexico	
16.	Check Ap	propriate Box To Indica	ate Nature of Notice, Report, or	O.L. D .	100000	
	NOTICE OF INTENT	ION TO:	t e			
TEST WATER SHO	TEST WATER SHUT-OFF PULL OR ALTER CASING				UBNT REPORT OF:	
PRACTURE TREAT	1 1	ULTIPLE COMPLETE	WATER SHUT-OFF	REPAIRING	WELL	
SHOOT OR ACIDIZE		BANDON*	PRACTURE TREATMENT	ALTERING	CABING	
REPAIR WELL	c	TANGE PLANS	SHOCTING OR ACIDIZING	ABANDONMI	ENT*	
Other) Change APD Completion or Recompleted Operations Clearly state all pertinent details, and give pertinent dates, in nent to this work. Completion or Recompleted operations of the subsurface locations and measured and true vertical operations of the subsurface locations and measured and true vertical operations.				its of multiple completion	OR Well	
Proposed work.	OR COMPLETED OPER	ATIONS (Clearly state all per	tinent details, and give pertinent date locations and measured and true vert	apletion Report and Log fo	orm.)	
_			changes to the dril			
1.	<u> </u>		e cased-hole only an urface with compensa selected segments.	nd consist of ited neutron a	a and	
2.	Casing program will consist of 2 joints (appoximately 88') 4 1/2" 11.60 lbm/ft N-80 at the top of the J-55 string. Procedure in APD called for 5 joints.					
3.	3. Cementing will be single stage, leading with 750 sacks of 65/35 Standard/Poz containing 12% Bentonite, 6.25 lbm/sx Gilsonite, 0.25 lbm/sx and 0.6% Halad-322, and tailing in with 150 sacks of Class "G" containing 6.25 lbm/sx Gilsonite, 8 lbm/sx Salt, 1/2 lbm/sx Flocele and 2% Calcium Chloride.					
•	. • *		REG	EINE		
I hereby certify tha	t the foregoing is tr	ue and correct	- MAI.	8 1902		
SIGNED			Petroleum Engineer	0 1393		
(This space for Fed	Prel or Service		Tecroreus Engraeer	Dec.	23, 1992	
	or State office u	a e)		APP	ROVED	
APPROVED BY CONDITIONS OF A	PPROVAT :-	TITLE		D		
JULIATIONS OF A	NOVAL, IF ANY	:		DATE	31 1002	
(2)		Jina Sanode	- Man Signed: STEPPEでは、			
		*C 1	D		MANAGER	
		Dee Instruction	ons on Reverse Side NMOCD	ANCA I	WANAGER	

le 18 U.S.C. Sestion 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the steed States any false. Detitious or fraudulent statements or representations as to any matter within its jurisdiction