Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31 1993

	OF THE INTERIOR ND MANAGEMENT	Expires: March 31, 1993
		5. Lease Designation and Serial No. NM 7/69 7
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.		6. If Indian, Aliottee or Tribe Name
Use "APPLICATION FOR I	PERMIT—" for such proposals	
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of Well Oil Gas Well Other		
Well Well Other 2. Name of Operator		8. Well Name and No.
COULTHURST MGT. + INVST. INC 3. Address and Telephone No.		JENNY # Z 9. API Well No.
		3064320894005Z 10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		
5EC. 28 SE. S.W. R.3. 18N. 990 F.S.L. 2310 F.E.L.		SOUTH SANLUZS 11. County or Parish, State
		The country of Parisar, under
U 3 ω		SANDOVOL
12. CHECK APPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTICE, REPO	RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
Π	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other	Dispose Water (Note: Report results of multiple completion on Well
13 Describe Pennand or Completed Opening (Cl. 1)		Completion or Recognition Report and Lanform
give subsurface locations and measured and true vertical	ertinent details, and give pertinent dates, including estimated date of startis depths for all markers and zones pertinent to this work.)"	ag any proposed work. If well is directionally drilled,
PROCEDURE:		
TO FILL H'S 10.54 CASTA	VG, FOLL FROM BOTTOM PER	era comment for too
VITTU KH C-3 OC 1K YH/COL	CEMENT SLURRY TO SURFACE	FORALION B 544
"115 100 11mb or 400 - 1114	SEMENI SLURRY TO SURFAC	<i>E.s.</i>
HE VOLUTE OF 344 OF 4/2	10.5# PIPE IS 53.648 Pr. (F.	MENT WILL BE ON
AND TO FILL CASING IF PRO	DUCING ZONE TAKES CEMENT	THROUGH PERFORATION
er er en er	the control of the co	200
and the second of the second o		
	*****	**************************************
	The second secon	and the second s
en e		the control of the co
the state of the s	grander of the second of the s	land to the material and the second lighter administration of material and another pulsar and another metallic
And the second of the second o	and the second s	and the second s
14. I hereby certify that the mezojag is true and correct		
Sign.	THE ACENT FOR COUNTHURST	Date 4-26-2004
(This/space or federal of State office use)	Lands and Mineral Resources	
Approved by attitue my Hester Conditions of approval, if any:	Title	Date 5-3-01
promises of approved to any.		

CONDITIONS OF APPROVAL FOR PERMANENT ABANDONMENT

Operator Coulthurst Well Name NMNM 71697

Jenny #1 PI 30-043-20894

- 1. Plugging operations authorized are subject to the "General Requirements for Permanent Abandonment of Wells on Federal Leases."
- 2. Notify Al Yepa (505) 289-3748, at the Cuba BLM Office prior to beginning plugging procedures.
- 3. Blowout prevention equipment is required.
- 4. The following modifications to your plugging program are to be made:

None

BLM CONDITIONS OF APPROVAL

The following surface rehabilitation Conditions of Approval must be complied with as applicable, before this well can be approved for final abandonment (see 43 CFR 3162.3-4). Surface rehabilitation work shall be completed within one year of the actual plugging date. Notification for completion of this work should be submitted with a Sundry Notice. Questions? Call Pat Hester at (505) 761-8786.

- 1. All fences, production equipment, purchaser's equipment, concrete slabs, deadman (anchors), flowlines, risers, debris and trash must be removed from the location. Non-retrieved flowlines and pipelines will be abandoned in accordance with State Rule 714. Information supporting the non-retrieval will be included in the subsequent report or final abandonment Sundry Notice.
- 2. Production pits will be closed according to the Unlined Surface Impoundment Closure Guidelines, as approved in the Environmental Assessment of December 1993. Any oil stained soils can be remediated on-site according to these guidelines or disposed of in a an approved facility.
- 3. The well pad will be shaped to the natural terrain and left as rough as possible. All compacted areas and areas devoid of vegetation shall be ripped/disked to a minimum of 12" in depth before reseeding.
- 4. Access roads will be shaped to conform to the natural terrain and left as rough as possible to deter vehicle travel. Access will be ripped to a minimum of 12" in depth, water barred and reseeded. All erosion problems created by the development must be corrected prior to acceptance of release. Water bars should be spaced as shown below along the fall line of the slope:

% Slope	Spacing Interval
Less than 20%	200'
2 to 5 %	150'
6 to 9 %	100'
10 to 15 %	50'
Greater than 15%	30'

- 5. All disturbed areas will be seeded with the prescribed certified seed mix (reseeding may be required). Seed mix must be certified weed free to avoid the introduction of noxious weeds. Refer to the original APD for seed mix.
 - 6. Notify Surface Managing Agency seven (7) days prior to seeding so that they may be present to witness.
- 7. The period of liability under the bond of record will not be terminated until the well is inspected and the surface rehabilitation approved.

Other Surface Managing Agencies (SMA's) may vary slightly in their restoration requirements. It is your responsibility, as the operator, to obtain surface restoration requirements from other SMA's. We need to be provided with a copy of these requirements. Any problems concerning stipulations received from other SMA's should be brought to us. On private land, a letter from the fee owner stating that the surface restoration is satisfactory will be provided to the office. Questions? Call Pat Hester at (505) 761-8786.