

Form 3160-5
(September 2001)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTSUNDY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.FORM APPROVED
OMB No. 1004-0135
Expires January 31, 2004

SUBMIT IN TRIPLICATE - Other instructions on reverse side

5. Lease Serial No.
NM 84664

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.
SAN ISIDRO 5-14

9. API Well No.
30-043-20870

10. Field and Pool, or Exploratory Area

11. County or Parish, State
Sandoval County, NM

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Pride Energy Company

3a. Address

P.O. Box 701950, TULSA, OK 74170

3b. Phone No. (include area code)

(918) 524-9200

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

UNIT Letter D: 660' FWL And 660' FWL of Section 12-20N
N 1450 FWL S01 PSC 5-20-2W 300

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input checked="" type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

We plan to demonstrate casing integrity for Temporarily Abandoning this well by running a packer within 100 feet of the uppermost perforations or production casing shoe and test to 500 pounds per square inch with a pressure drop of not more than 10% for 30 minutes.

It is being proposed that these operations be conducted by July 26, 2002, or possibly sooner.

Adjud	2mg
Engr	/
Geol	
Gen	
Appvl	/

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

By: Pride Energy Co., Inc.

Title: General Partner

By: Matthew L. Pride

Title: President

Signature

Matthew L. Pride

Title

Date

7/23/02

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Lands and

Mineral Resources

Date

7/26/02

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

* Well will be plugged in 90 days if test fails
Test will be witnessed

IN REPLY REFER TO
3162.3-1 (017)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT
Albuquerque Field Office
435 Montano N.E.
Albuquerque, New Mexico 87107

Company Pride Energy Company

Well No. San Isidro No. 5-14

Location 1650' FWL & 501' FSL Sec.12, T20N, R2W, NMPM

Lease No. NMNM-84664

Government Contacts:

Bureau of Land Management , Albuquerque Field Office Office 505.761.8700
Manager: Steve Anderson, Assistant Field Manager 505.761.8982
Petroleum Engineer: Brian W. Davis 505.761.8756, Home 505.323-8698,
Pager 505.969.0146, Cell 505.249.7922,
Petroleum Engineering Technician: Al Yepa 505.321.4426 cell and 505.289.3748
Al Attencio 505.362.2843
BLM Geology / Environmental Contact: Patricia M. Hester 505.761.8786

GENERAL REQUIREMENTS
FOR
OIL AND GAS OPERATIONS ON FEDERAL AND INDIAN LEASES

1. Plugging operations authorized are subject to the "General Requirements for Permanent Abandonment of Wells on Federal and Indian Leases."

2. Blowout prevention equipment is required.

3. The sundry is approved with the following change:

If the test fails, the well will be plugged within 90 days. A plugging plan will need to be approved prior to plugging.