

NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL		NOTICE OF INTENTION TO PLUG BACK		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE	X	NOTICE OF INTENTION TO ACIDIZE		NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE	X	NOTICE OF INTENTION (OTHER) Sand Frac	X	NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICO

Farmington, New Mexico
(Place)


April 19, 1956
(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the.....

Great Western Drilling Company **Chaco Unit** Well No. **2** in **0**
 (Company or Operator) **LEASE** (Unit)
SW $\frac{1}{4}$ **SE** $\frac{1}{4}$ of Sec. **16**, T. **23N**, R. **8W**, NMPM, **Wildcat** Pool
 (40-acre Subdivision)
San Juan County.

FULL DETAILS OF PROPOSED PLAN OF WORK
 (FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)



The Chaco Unit No. 2 will be worked over as follows:

A cable tool unit will be moved on the location April 23, 1956. The rods and tubing will be pulled and the well will be cleaned out to 5090(P.B. T.D.).

The casing perforations (4911-41, 4976-87, 5019-29, 5052-59) will be squeezed off, logs run, and the casing will be re-perforated.

The well will be fractured with sand and oil down the casing in two or three stages.

Approved..... **4-24**, 19 **56**
 Except as follows:

Great Western Drilling Company
 Company or Operator

By.....

Position..... **Div. Prod. Supt.**

Send Communications regarding well to:

Approved
OIL CONSERVATION COMMISSION

By.....

Title..... **Oil and Gas Inspector Dist. #3.**

Name..... **Great Western Drilling Company**

Address..... **211 1/2 West Main Street, Farmington, N.M.**

OIL CONSERVATION COMMISSION

100-443887-100

No. C-493-10-10

[illegible]

[Faint, illegible handwritten notes]

1. The first step in the process is to identify the problem or issue that needs to be addressed. This involves gathering information and understanding the context of the problem.

Fig. 2. ΔT_{max} vs. ΔT_{min} for the Fe_2O_3 and Fe_3O_4 systems. The solid line is the theoretical curve for the Fe_2O_3 system and the dashed line is the theoretical curve for the Fe_3O_4 system.

[illegible]

Dec 9th

1. The first step in the process is to identify the problem or issue that needs to be addressed. This involves gathering information and understanding the context of the problem.

1. The first step in the process is to identify the problem or issue that needs to be addressed. This involves gathering information and understanding the context of the problem.

Transcript