Form 9-331 (May 1903)		JNITED STATES IENT OF THE I		SUBMIT IN TRIPLICAT (Other instructions on verse side)	5. LEASE DESIGNATION AND SERIAL NO.
GEOLOGICAL SURVEY					NOO-C-14-20-2954
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.) 1. OIL GAS WELL OTHER Dryhole 2. NAME OF OPERATOR					6. IF INDIAN, ALLOTTEE OR TRIBE NAME
					Navajo Tribal
					7. UNIT AGREEMENT NAME
					8. FARM OR LEASE NAME
	Woods Petroleum Corporation				
3. ADDRESS OF OPERATOR	3. ADDRESS OF OPERATOR				
P. O. Box 1866	P. O. Box 18667, Oklahoma City, Oklahoma, 73118				
P. O. Box 18667, Oklahoma City, Oklahoma, 73118 1. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)					10. FIELD AND POOL, OR WILDCAT
At surface					Wildcat
					11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
1650' FNL, 198	0¹ FWL (SE	NW)			
14. PERMIT NO.		15 PIRVATIONS (Chart	shathan pp. pp.	on etc.)	22-23N-14W 12. COUNTY OR PARISH 13. STATE
14. FERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5867' GL, 5881' KB			
		· · · · · · · · · · · · · · · · · · ·			San Juan New Mexico
16.	Check Ap	propriate Box To Ind	licate Natur	e of Notice, Report, or	Other Data
NO	TICE OF INTENT	ON TO: SUBSEQU			QUENT REPORT OF:
TEST WATER SHUT-OFF	. P	JLL OR ALTER CASING	7	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	м	ULTIPLE COMPLETE		FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	A	BANDON*		SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	c1	HANGE PLANS	_	(Other)	
(Other)				Completion or Recon	its of multiple completion on Well apletion Report and Log form.)
proposed work. If nent to this work.) *	well is direction	ally drilled, give subsur	face locations	ans, and give pertinent date and measured and true vert	es, including estimated date of starting any ical depths for all markers and zones perti-
reached a total deptł Laterolog, Compensa	n of 9,703' ited Format s。Permiss	, driller's measu ion Density Log, on to plug and a	rement, o and drill bandon w	n 4-21-71. Evalud stem test (Dakota)	cemented to surface. We ation using Dual Induction-showed an absence of r. M. L. Seelinger with the
60 sack plug	9500-970	J1			
30 sack plug	9200-930				
37 sack plug	6950-707				
30 sack plug	5550-565	18 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
45 sack plug	4250-440				
45 sack plug	3300-345				A second
10 sack plug	Surface pi				MAY 5 1/4/1
to suck plug	Solitace pi	he.			1000
Welded on steel plate	e and mark	ed.			DIST. 3
	» / ((7			
18. I hereby certify that the	ie Foregoing i	rue and correct			
SIGNED	LAND	TITI	E Vice	President	DATE April 28, 1971
(This space for Federa	l or State office	use)			
APPROVED BYCONDITIONS OF APP	ROVAL, IF AN	TITI	æ		DATE