

COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Dome Petroleum Corporation		8. Farm or Lease Name Santa Fe 6-20-21-8
3. Address of Operator %Minerals Management Inc., Suite 105, 501 Airport Drive, Farmington, New Mexico 87401		9. Well No. 6
4. Location of Well UNIT LETTER <u>B</u> <u>990</u> FEET FROM THE <u>North</u> LINE AND <u>2310</u> FEET FROM <u>East</u> LINE, SECTION <u>20</u> TOWNSHIP <u>21N</u> RANGE <u>8W</u> NMPM.		10. Field and Pool, or Wildcat Snake Eyes Entrada
15. Elevation (Show whether DF, RT, GR, etc.) 6554' GR, 6566' KB		12. County San Juan

### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

#### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

#### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>


17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-15-77 Operator plugged and abandoned well as follows:

Plug No. 1	5510'-5710'	(200')	75 sx
Plug No. 2	4400'-4550'	(150')	75 sx
Plug No. 3	3240'-3390'	(150')	70 sx
Plug No. 4	2370'-2520'	(150')	70 sx
Plug No. 5	800'-952'	(150')	60 sx
Plug No. 6	185'-285'	(100')	35 sx
Plug No. 7	0'-30'	(30')	15 sx

Marker was set at 4:30 p.m. The pit has been fenced and location will be cleaned.

**CONFIDENTIAL**



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Area Manager DATE July 18, 1977

APPROVED BY [Signature] TITLE Minerals Management DATE July 18, 1977

CONDITIONS OF APPROVAL, IF ANY:

5-28-78