

## OIL CONSERVATION DIVISION

STATE OF NEW MEXICO  
GEOLOGY AND MINERALS DEPARTMENTP. O. BOX 2088  
SANTA FE, NEW MEXICO 87501Form C-102  
Revised 10-1-78

All distances must be from the outer boundaries of the Section.

Dugan Production Corporation			Lease		Well No.		
			Seoul		88		
Tract	Section	Township	Range	County			
A	9	23 North	10 West	San Juan			
Footage Location of Wells:							
0	feet from the	North	line and	330	feet from the	East	line
Level Elev.	Producing Formation		Pool		Dedicated Acreage:		
20	Gallup		South Bisti-Gallup		80		Acres

Outline the acreage dedicated to the subject well by colored pencil or hatchure marks on the plat below.

If more than one lease is dedicated to the well, outline each and identify the ownership thereof (both as to working interest and royalty).

If more than one lease of different ownership is dedicated to the well, have the interests of all owners been consolidated by communitization, unitization, force-pooling, etc?

☐ Yes ☐ No If answer is "yes," type of consolidation \_\_\_\_\_

If answer is "no," list the owners and tract descriptions which have actually been consolidated. (Use reverse side of this form if necessary.) \_\_\_\_\_

No allowable will be assigned to the well until all interests have been consolidated (by communitization, unitization, forced-pooling, or otherwise) or until a non-standard unit, eliminating such interests, has been approved by the Division.

RECEIVED

JAN 10 1986

OIL CON. DIV.

DIST. 3

SEC. 9

530'  
Dugan Prod. Corp.  
Navajo Allotted  
Ls# N00-C-1420-  
7312

## CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief.

Jan 1 Jan  
Name

Jim L. Jacobs

Position

Geologist

Company

Dugan Production Corp.

Date

1-8-86

EDGAR L. RISENHOOVER  
NEW MEXICO  
5972  
I certify that the location shown on this plat was obtained from field notes I made personally or under my supervision, and that the same is true and correct to the best of my knowledge and belief.

Date Surveyed

October 2, 1985

Registered Professional Engineer  
and/or Land SurveyorEdgar L. Risenhoover  
5972