ovember 1983)	1 Ruth Ross STATES	8UBMIT-IN TRIPLICATE® (Other Instructions on re-	
merly 9–331) .		verse mue)	NM 36355
SUNDRY NOTICES AND (Do not use this form for proposals to drill or use "APPLICATION FOR PE	REPORTS ON to deepen or plug back to	to a different reservoir.	G. IF INDIAN, ALLOTTEE OR TEINE NAME
OIL X CAS OTHER			7. UNIT AGREEMENT NAME
NAME OF OPERATOR	7 A	FARMINGTON, NEW MEXICO	8. FARM OR LEASE NAME
DUGAN PRODUCTION CORP.			Baby Ruth 9. WHLL NO.
P.O. Box 420, Farmington, NM			1
LOCATION OF WELL (Report location clearly and in a See also space 17 below.) At surface 330' FNL & 330' FWL	ecordance with any State	requirements.*	Wildcat Mesa Verde 11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA
	(6)		Sec. 33, T23N, R11W, NMPM
6185 G	NS (Show whether DF, RT, C	ik, etc.)	San Juan NM
Check Appropriate Bo	ox To Indicate Natur	e of Notice, Report, or C	
NOTICE OF INTENTION TO:	1		JENT EMPORT OF:
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly proposed work. If well is directionally drilled, generated to this work.)*	I.ETE	Completion or Recomplails, and give pertinent dates,	of multiple completion on Well letion Report and Log form.) including estimated date of starting any
#4. <u>Spudded</u> Drilled to 20 <u>casing</u> (T.E. 75 sx class 88.5 cu.ft.	d a 9-3/4" 00'. <u>Ran 6</u> 197.30') <u>set</u> "B" + 2% Ca). P.O.B	lazar Drilling hole @ 6:00 P. jts. 7" OD, 20# @ 199' G.L. C Cl ₂ (total ceme	.M. 4-28-89. , 8 Rd, ST&C emented with ent slurry = M. 4-29-89.
Pressure tes minutes - hel	ted BOP and Ld OK.	surface casing	600 psi 30
			4 0 - LUNO 2 1989
	CONFIDENT	TIAL	01 00% DIV.
hereby certify that the foregoing is true and corre			. 5 1 00
Jim L. Jacobs	TITLE G	eologist	
This space for Federal or State office use)			ACCEPTED FOR RECORD
PPROVED BY	TITLE	oce	MAY 0 8 1989 FARMINGTON RESOURCE AREA

*See Instructions on Reverse Side

BY EV