## Submit 3 Copies to Appropriate District Office

CONDITIONS OF APPROVAL, IF ANY:

## State of New Mexico Energy, Minerals and Natural Resources Department

1
Form C-103
Revised 1-1-89
Wastred 1-1-9A

ELL API NO.	
30-045-27242	

DISTRICT I P.O. Box 1980, Hobbs, NM 88240	P.O. Box 1980, Hobbs, NM 88240  P.O. Box 2088  DISTRICT II  Santa Fe. New Mexico, 87504-2088		WELL API NO.	
			30-045-27342	
P.O. Drawer DD, Artosia, NM 88210	•		5. Indicate Type of Lease	
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM \$7410		STATE FEE X  6. State Oil & Gas Lease No.		
( DO NOT USE THIS FORM FOR PRO	CES AND REPORTS ON W PPOSALS TO DRILL OR TO DEEP IVOIR. USE "APPLICATION FOR 101) FOR SUCH PROPOSAL ST.	EN OR RILIG BACK TO A	7. Lease Name or Unit Agreement	Name
1. Type of Well: OIL GAS WELL WELL X	In!	SEP 1 8 1998	Santa Fe 20	
2. Name of Operator  Merrion Oil & Gas Cor	poration (A)	CON. DIV.	8. Well No. 004 (7840)	
3. Address of Operator			004 (7840)  9. Pool same or Wildow	
610 Reilly Avenue, Fa	rmington, NM 87401-	DIST. 3	Snake Eyes Dakota	'D' (85520)
Unit Letter I : 231		Line and	Feet Prom The	east Line
Section 20	Township 21N	Range 8W	<b>NMPM</b> San Juan	County
	777777	er DF, RKB, RT, GR, etc.)	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	
11. Check A	Appropriate Box to Indicate			
NOTICE OF INT	ENTION TO:		SEQUENT REPORT O	F.
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CA	_
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING		MANDONMENT X
PULL OR ALTER CASING	<u> </u>	CASING TEST AND CE		MINDOINIMENT [==]
OTHER:		OTHER:		
				U
<ol> <li>Describe Proposed or Completed Operation</li> <li>Work) SEE RULE 1103.</li> </ol>	ions (Clearty state all pertinent details,	and give pertinent dates, includ	ing estimated date of starting any pro	posed
1 1	A-Plus Well Service Rig #4). RD nented very tight. ND WH, NU B	OCS. Same propiem with hi	hing hanger TOU with 66 -4- 3	- CO 0/033 4
tueling (+1/3 ±). I unit stuck	in seating nipple. Tubing pulled v :00 AM 9/14/98 (H. Villeneva on :	vet (water) from opprov. 200	' to 4178'. Tubing looks OK. SI	DON.
displace. Spot Plug #1 from 4 3338'. Break circulation and p to 926'. Break circulation and	tbing. TIH with 502' of 1-1/4" IJ: t 4647'. Pump 30 bbls water ahea 547'-3918' as a balanced plug. To ressure test to 500 psi—test well. mix 12 sxs Class 'B'. Spot balance out casing valve. TOH with resumocod on location.	OH to 3410'. WOC – Plug # Mix 12 sxs Class 'B' and sp	m of well. Mix 33 sxs Class 'B'; 1. TIH, tag plug #1 at 4012', good balanced Plug #2 from 3335'-	at 15.4# and od tag. TOH to 3235'. TOH, LD
Open BOPs, TOC at 10'. ND I RDMOL.	BOPs. Cut off WH. Set marker, T	OC in bradenhead at 10', ca	sing 10'. Marker cemented with	15 sxs Class 'B'.
I hereby certify that the information above is true	and complete to the best of my knowledge a	nd belief.		
SIGNATURE STO	/)/\1	ma Drlg & Prod M	anager9/	17/98
TYPE OR FRINT NAME	ven S. Dunn		TELEPHONE N	
(This space for State Use)			1 CALEST TRATE IN	
ORIGINAL SIGNED BY	E. VILLANUEVA	SEPUTY OIL & GAS INSP	ECTOR, DIST. #3 MAR	3 0 199 <b>g</b>
APPROVED BY		TILE	DATE	-