Submit 3 Copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Revised 1-1-89

- DATE -

DISTRICT I P.O. Box 1980, Hobbs, NM 88240		ATION DIVISION ox 2088	WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210		exico 87504-2088	30-039-05238 5. Indicate Type of Lease
DISTRICT III			STATE XX FEE
1000 Rio Brazos Rd., Azzec, NM 87410			6. State Oil & Gas Lease No. E-1207
(DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVO	ES AND REPORTS ON DSALS TO DRILL OR TO DI DIR. USE "APPLICATION FO 1) FOR SUCH PROPOSALS	EEPEN OR PLUG BACK TO A OR PERMIT FEB 2 0 123	7. Lease Name or Unit Agreement Name
. Type of Well: Oil GAS WELL WELL X	OTHER	OIL GOM. D	NCRA State
. Name of Operator Benson-Montin-Greer Dril	lling Corn	ප්යාග ව	8. Well No.
3. Address of Operator	tring corp.		9. Pool name or Wildcat
4900 College Boulevard,	Farmington, NM	87402	Ballard Pictured Cliffs
Unit Letter :1816	Feet From The SOU	th Line and	990 Feet From TheeastLir
Section 36	Township 24N	Range 6W	NMPM Rio Arriba County
		whether DF, RKB, RT, GR, etc.) 6829 †	
11. Check Ar	opropriate Box to Ind	icate Nature of Notice,	Report or Other Data
NOTICE OF INTE			BSEQUENT REPORT OF:
ERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	X ALTERING CASING
ERFORM REMEDIAL WORK EMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLI	
			NG OPNS. PLUG AND ABANDONMENT
EMPORARILY ABANDON		COMMENCE DRILLI	NG OPNS. PLUG AND ABANDONMENT
EMPORARILY ABANDON ULL OR ALTER CASING OTHER:	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER:	NG OPNS. PLUG AND ABANDONMENT
EMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operation work) SEE RULE 1103.	in preparation to making gas. Fir to 2296'. Blew	COMMENCE DRILLI CASING TEST AND OTHER: Leads, and give pertinent dates, income to plug using production of the produc	PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed uced water to load the bulldog t, ran string of 1-1/4" tubing atter recovered. Turned well
EMPORARILY ABANDON OULL OR ALTER CASING OTHER: 12 Describe Proposed or Completed Operation work) SEE RULE 1103. Cleaned out to 2311' TD bailer. Well commenced (71 joints), open-ended	in preparation to making gas. Fir to 2296'. Blew 20, 1999. Well	CASING TEST AND OTHER: Co plug using production of the cleaning out well until load was producing approximately a	PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed uced water to load the bulldog t, ran string of 1-1/4" tubing atter recovered. Turned well

APPROVED BY ---