Form 9-881 a (Feb. 1961)

## \$ 5**0** . 30

## (SUBMIT IN TRIPLICATE)

Land Office Santa Fo					
Lesse No. SF	080715-A				
Unit					

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WEDER ENVE	لــــــــــــــــــــــــــــــــــــــ										
	CI IN	JDRV	NOTICES	AND	DEDODTC	ON	TX AFTE	E.O	n N	7 E	,- 11

NOTICE OF INTENTION TO DRILL SUBS	- 111
	SEQUENT REPORT OF WATER SHUT-OFF HIT 13 1962
	EQUENT REPORT OF SHOOTING OR ACIDIZING.
	EQUENT REPORT OF ALTERING CASING
	EQUENT REPORT OF ABANDONMENT
	LEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL.	
(INDICATE ABOVE BY CHECK MARK NATURE OF	REPORT, NOTICE, OR OTHER DATA)
***************************************	November 9 19 62
ngaga	ne and 1850 ft. from $\frac{E}{W}$ line of sec. 30
NE/4 Section 30 24 North 1 West	NAPA
(1/4 Sec. and Sec. No.) (Twp.) (Range)	(Meridian)
So Blanco Pictured Cliffs Rio Arriba (County or Subdivision	New Mexico
Ground (County or Subdivision	(State or Territory)
The elevation of the denical floor above sea level is	510 ft.
DETAILS OF	· · ·
State names of and expected depths to objective sands; show sizes, weights, ing points, and all other import	and lengths of proposed casings; indicate mudding jobs, cement-
	ant proposed work)
Subject well spudded 5-23-61. 8 5/8" surface with 50 sacks. Total depth of 3390 reached come out of hole, to run log, drill pipe streament trying to release drill piep which restreament to salvage drill pipe unsuccessful.	May 29, 1961. While attempting to uck at 2430'. Several days were suited in the derrick collapsing.
Subject well spudded 5-23-61. 8 5/8" surfaction of 50 sacks. Total depth of 3390 reached come out of hole, to run log, drill pipe stream trying to release drill piep which restreampt to salvage drill pipe unsuccessful. It is our intention to plug hole, pump coment surface, if plugging procedure not agree	May 29, 1961. While attempting to uck at 2430'. Several days were suited in the derrick collapsing.  Int through drillpipe and set applicable, please advise.
Subject well spudded 5-23-61. 8 5/8" surface with 50 sacks. Total depth of 3390 reached come out of hole, to run log, drill pipe streament trying to release drill piep which restreament to salvage drill pipe unsuccessful. It is our intention to plug hole, pump camerate surface, if plugging procedure not agree a surface. If plugging procedure not agree a surface. Shar-Alan Oil Company	ce casing set at 104' and cemented May 29, 1961. While attempting to uck at 2430'. Several days were suited in the derrick collapsing.  Int through drillpipe and set applicable, please advise.
Subject well spudded 5-23-61. 8 5/8" surface with 50 sacks. Total depth of 3390 reached come out of hole, to run log, drill pipe straight trying to release drill piep which restrempt to salvage drill pipe unsuccessful. It is our intention to plug hole, pump camerat surface, if plugging procedure not agree it surface, if plugging procedure not agree.	May 29, 1961. While attempting to uck at 2430'. Several days were suited in the derrick collapsing.  Int through drill pipe and set applicable, please advise.  NOV 1.4 1962  DIST. 3
Subject well spudded 5-23-61. 8 5/8" surface with 50 sacks. Total depth of 3390 reached come out of hole, to run log, drill pipe stream trying to release drill pipe which restream to salvage drill pipe unsuccessful. It is our intention to plug hole, pump camer it surface, if plugging procedure not agree a surface. If plugging procedure not agree to salvage drill Company Shar-Alan Oil Company S	May 29, 1961. While attempting to uck at 2430'. Several days were suited in the derrick collapsing.  Int through drill pipe and set pip
Subject well spudded 5-23-61. 8 5/8" surface with 50 sacks. Total depth of 3390 reached come out of hole, to run log, drill pipe stream trying to release drill pipe which restream to salvage drill pipe unsuccessful. It is our intention to plug hole, pump camer it surface, if plugging procedure not agreed that this plan of work must receive approval in writing by the company  Shar-Alan Oil Company  Address 1402 Denver U. S. National Center	May 29, 1961. While attempting to uck at 2430'. Several days were suited in the derrick collapsing.  Int through drill pipe and set plus bable, please advise.  NOV 1.4 1962  NOV 1.4 1962  RIGHAR SIGNED E.  RIGHARD S. HUNE
Subject well spudded 5-23-61. 8 5/8" surface with 50 sacks. Total depth of 3390 reached come out of hole, to run log, drill pipe streament trying to release drill piep which restreament to salvage drill pipe unsuccessful. It is our intention to plug hole, pump camerat surface, if plugging procedure not agree to surface, if plugging procedure not agree of surface. Shar-Alan Oil Company	May 29, 1961. While attempting to uck at 2430'. Several days were suited in the derrick collapsing.  Int through drill pipe and set applicable, please advise.  NOV1 4 1962  DIST. 3  PRICHARD S. HUNE