

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen a well. Plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐

2. NAME OF OPERATOR
Grace Petroleum Corporation

3. ADDRESS OF OPERATOR 3 Park Central, Suite 200
1515 Arapahoe Street, Denver, CO 80202

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1500' FSL and 1550' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☒
(other) ☐

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

RECEIVED

MAR 05 1982

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

5. LEASE
SF-078563

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Kenney

9. WELL NO.
3

10. FIELD OR WILDCAT NAME
Escrito Field

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 23, T24N-R7W

12. COUNTY OR PARISH
Rio Arriba

13. STATE
New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
6710 DF, 6698' GL

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Propose to abandon well due to severely corroded casing. Estimated start date April 1, 1982.

1. Kill Gallup zone, nipple down wellhead, nipple up BOP.
2. POOH with tubing, laying down cement plugs as follows:

5663' (PBTD)-5000' 55 SX
~~4000'-4240'~~ ~~4400'-4160'~~ 20 SX
* ~~1500'-1740'~~ 20 SX
Surface 10 SX

see attached modifications.

3. Abandoned well marker to be installed as per New Mexico Rule 202.
4. Surface to be reclaimed to BLM specifications.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct.

SIGNED Donald J. Feltner TITLE Sr. Operations Engineer DATE March 1, 1982

APPROVED BY _____ (This space for Federal or State office use)
CONDITIONS OF APPROVAL _____ TITLE _____ DATE _____

AS AMENDED

APPROVED

MAR 12 1982

JAMES F. SIMS

DISTRICT ENGINEER

See Instructions on Reverse Side

NMOCC

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U. S. GEOLOGICAL SURVEY
Drawer 600
Farmington, New Mexico 87499-00600

Attachment to Notice of
Intention to Abandon

Re: Permanent Abandonment

Well: 3 Kenney

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."
2. The Farmington office (telephone (505) 325-4572) is to be notified in sufficient time for a representative to witness all plugging operations.
3. Blowout prevention equipment is required.
4. In addition to normal filling of pits and cleanup of location, additional surface restoration work may be required, i.e. ripping of pad and/or access road, reseeding, etc. We have asked the Bureau of Land Management for the surface restoration requirements for this well and we should be able to furnish you these requirements within 30 days. After plugging the well and before making final clean-up, you should contact this office unless you have already been advised as to what additional surface restoration work is required.
5. The following modifications to your plugging program are to be made (when applicable):
 - a) Perforate 4½" casing at 3607' and spot cement plug inside and outside casing from 3607' to 3507' to cover top of Mesaverde.
 - b) Perforate 4½" casing at 2075' and spot cement plug inside and outside casing from 2075' to 1975' to cover top of Pictured Cliffs.
 - c) Perforate 4½" casing at 1795' and spot cement plug inside and outside casing from 1795' to 1695' to cover top of Fruitland.
 - d) Perforate 4½" casing at 1393' and spot cement plug inside and outside casing from 1393' to 1293' to cover top of Ojo Alamo.
 - e) Perforate 4½" casing at 265' and spot cement plug inside and outside casing from 265' to 165' to cover surface casing shoes.

Office Hours: 7:30 A.M. to 4:15 P.M.