
Form 9-331 a (Feb. 1951)



(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

	-		
Land Office	ិករាជ	a Fe	
Lease No	O.Y.B.D.	13	
Unit Lizz	to teh	Heat to	

SUNDRY NOTICES AND REPORTS ON WELLS

	UBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	UBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	JBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL SL	JBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	JBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	JPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	U.S. GEOLOGICAL ST. C.
	The state of the s
(INDICATE ABOVE BY CHECK MARK NATURE	OF REPORT, NOTICE, OR OTHER DATA)
	August 22 , 19 55
Vell No. 37 is located 1090 ft. from [N]	line and \mathbf{m} ft. from \mathbf{E} line of sec. \mathbf{m}
Sec • 21 24 11 (Kange) (Range)	(Meridian)
Blanco Pictured Cliffs Rio Arriba	Ser Series
(Field) (County or Subdiv	
Ground	•
ne elevation of the derner liber above sea level is	<u>7113</u> ft.
DETAILS O tate names of and expected depths to objective sands; show sizes, weigh	hts, and lengths of proposed casings; indicate mudding jobs, cement-
ing points, and all other im	
is intended to Plug and Abereira this we	all in the following maxim.
1. Squeeze perforations and being top of	
2. Cut casing at approximately 2000' and	e venta.
3. Set 50' cement plugamone caming stub.	· intro
4. If casing is cut below Ojo Alamo - pu	th 3501 annuary william decrease
top of 0,10 Alamo.	to you consists from sicilosis
5. Set cement plug from 125 to 75.	
5. Set cement plug from 125 to 75.	
5. Set cement plug from 125 to 75.	
Set cement plug from 125 to 75.	
Set cement plug from 125 to 75.	
Set cement plug from 125 to 75.	
Set cement plug from 125 to 75.	
Set coment plug from 125 to 75. Set coment plug at surface. Set b' x 4" pipe as permanent marker. I understand that this plan of work must receive approval in writing	
Set coment plug from 125 to 75. Set coment plug at surface. Set 4' x 4" pipe as permanent marker. I understand that this plan of work must receive approval in writing	
Set coment plug from 125 to 75. Set coment plug at surface. Set 4' x 4" pipe as permanent marker. Tunderstand that this plan of work must receive approval in writing ompany El Paso Hatural Cas Compan;	
Set coment plug from 125 to 75. Set coment plug at surface. Set b' x 4" pipe as permanent marker. I understand that this plan of work must receive approval in writing ompany El Paso Hatural Cas Compan;	
Set coment plug from 125 to 75. Set coment plug at surface. Set b' x b" pipe as permanent marker. I understand that this plan of work must receive approval in writing ompany. El Paso Hatural Cas Compan;	by the Geological Survey before operations may be commenced.
Set coment plug from 125 to 75. Set coment plug at surface. Set b' x 4" pipe as permanent marker. I understand that this plan of work must receive approval in writing ompany El Paso Natural Cas Compan; ddress ———————————————————————————————————	
Set coment plug from 125 to 75. Set coment plug at surface. Set 4' x 4" pipe as permanent marker. I understand that this plan of work must receive approval in writing ompany El Paso Hatural Cas Compan;	by the Geological Survey before operations may be commenced.