

3 OCD Aztec 1 HRR 1 HLB 1 RR

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-85

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E-6833-11	
7. Unit Agreement Name	
Escrito Gallup Unit	
8. Farm or Lease Name	
9. Well No.	
17 (formerly State 1-16)	
10. Field and Pool, or Willacat	
Escrito Gallup	
12. County	
Rio Arriba	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name	
2. Name of Operator		Escrito Gallup Unit	
3. Address of Operator		8. Farm or Lease Name	
BCO, Inc.		9. Well No.	
135 Grant, Santa Fe, NM 87501		17 (formerly State 1-16)	
4. Location of Well		10. Field and Pool, or Willacat	
UNIT LETTER M 660 FEET FROM THE South LINE AND 400 FEET FROM		Escrito Gallup	
THE West LINE, SECTION 16 TOWNSHIP 24 N RANGE 7 W NMPM.			
15. Elevation (Show whether DF, RT, GR, etc.)		12. County	
7260 GR		Rio Arriba	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒
 TEMPORARILY ABANDON ☐
 PULL OR ALTER CASING ☐
 OTHER ☐

PLUG AND ABANDON ☐
 CHANGE PLANS ☐
 OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
 COMMENCE DRILLING OPNS. ☐
 CASING TEST AND CEMENT JOB ☐
 OTHER ☐
 ALTERING CASING ☐
 PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Suspect well has casing failure. Called Ernie Busch with the OCD and discussed plans to locate hole and repair. Will set bridge plug above perforations and go up hole testing with packer until hole is located. When locate hole will squeeze with cement and place well back in production. Ernie Busch gave permission to proceed with repair.

RECEIVED
 JUL 22 1988
 OIL CON. DIV
 DIST. 3

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Elizabeth B. Keeshan TITLE Vice President DATE 7/21/88

Original Signed by FRANK T. CHAVEZ

APPROVED BY _____

TITLE SUPERVISOR, DISTRICT 3DATE JUL 22 1988

CONDITIONS OF APPROVAL, IF ANY: