

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME Escrito Gallup Unit	
2. NAME OF OPERATOR BCO Inc.		8. FARM OR LEASE NAME Escrito Gallup Unit	
3. ADDRESS OF OPERATOR 135 Grant Avenue, Santa Fe, New Mexico 87501		9. WELL NO. 414 (Judy 1)	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 790 FEL 790 FSL Sec 17 T24N R7W NMPM		10. FIELD AND POOL, OR WILDCAT Wildcat	
11. SEC, T, R, M, OR BLK. AND SURVEY OR AREA Sec 17, T24N, R7W NMPM		12. COUNTY OR PARISH Rio Arriba	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) GR 7305	
16. COUNTY OR PARISH N M		17. STATE N M	

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PCLL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Within the next sixty days we will carry out the following work:

Before the well is abandoned we will test existing Chacra perforations (3589-3596) by swabbing. If formation produces gas, we will leave well in position to produce and leave shut in until there is a market for gas. If formation produces oil and casinghead gas, we have a market for both and will place well in production.

If swabbing shows no economic quantities of oil or gas, we will proceed with plugging and abandonment procedures.

In plugging the well we will follow one of the alternative programs laid out by Errol Becher on May 7, 1986. As soon as the economic decision has been made to determine which plugging alternative we will select, we will file an additional sundry notice of intention to abandon which details the abandonment program we will follow.

Present PBTD: 3705'
Formation Tops: Ojo Alamo 1910'
Kirtland 2102'
Picture Cliffs 2595'
Chacra 3396'

18. I hereby certify that the foregoing is true and correct

SIGNED Elizabeth B. Keeshan TITLE Comptroller

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

*See Instructions on Reverse Side

NMOC

RECEIVED
MAY 21 1986
OIL CON. DIV.
APPROVED
DATE 5/8/86
MAY 15 1986
DATE
J. B. Keeshan
AREA MANAGER
FARMINGTON RESOURCE AREA