

THOMAS A. DUGAN

Registered Professional Engineer

1007 North Dustin • Phone DAvis 5-9184
Farmington, New Mexico


March 9, 1961

Mr. Emery Arnold
New Mexico Oil Conservation Commission
1000 Rio Brozas Road
Aztec, New Mexico


Dear Mr. Arnold:

Redfern & Herd's Largo Spur 1-A located in the SE $\frac{1}{4}$ of
Section 14, Township 24 North, Range 7 West, Rio Arriba
County, New Mexico, was first delivered February 21, 1961.
There were 782.73 barrels of unrecovered load oil when
the well was first delivered. We are requesting a gas
allowable to recover our load oil.

Very truly yours,


Thomas A. Dugan

TAD/mwf



THOMAS A. DUGAN

Registered Professional Engineer

1007 North Dustin • Phone DAvis 5-9184
Farmington, New Mexico


March 9, 1961

Mr. Emery Arnold
New Mexico Oil Conservation Commission
1000 Rio Brozas Road
Aztec, New Mexico


Dear Mr. Arnold:

Redfern & Herd's Largo Spur 1-A located in the SE $\frac{1}{4}$ of
Section 14, Township 24 North, Range 7 West, Rio Arriba
County, New Mexico, was first delivered February 21, 1961.
There were 782.73 barrels of unrecovered load oil when
the well was first delivered. We are requesting a gas
allowable to recover our load oil.

Very truly yours,


Thomas A. Dugan

TAD/mwf



THOMAS A. DUBAN

Registered Professional Engineer

1007 North Dustin Phone DAVIS 5-9184
Farmington, New Mexico

1961

Mr. James H. ...
New Mexico ...
...
...
...

...

...
...
...
...
...
...
...

...

[Handwritten signature]

...

