NO. OF COPIES RECEIVED	1.3						Form C-10	13
DISTRIBUTION							Supersede	
SANTA FE	1,1		NEW MEXICO O	II CONS	ERVATION COMMISSI	ON	C-102 and	
FILE	171			ic cons	CRYATION COMMISSI	ON	Effective	1-1-02
U.S.G.S.	1 1	_					5a. Indicate T	vpe of Legse
LAND OFFICE	+						State X	Fee
OPERATOR .	+,1	 						Gas Lease No.
OPERATOR	1 4 1						E-120	i
 	C1 13	IDDV NOTICE	C 4110 0500			- 	***********	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEFFER OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)								
OIL X GAS		OTHER-					7. Unit Agree	nent Name
2. Name of Operator							8. Form or Le	ase Name
J. Gregory Merrion & Associates								ate
3. Address of Operator								
P.O. Box 507, Farmington, New Mexico 87401								
4. Location of Well		•					10. Field and	Pool, or Wildcat
		990 -		Woot	LINE AND1650		Devils Fo	ork Gallup-MesaVe
UNIT LETTERL	• •	FI	ET FROM THE	MESL	LINE AND	FEET FROM	Tillin.	minimi
THE South	LINE, SI	естіон <u>16</u>	TOWNSHIP	24	N RANGE 6W	NMPM.		
	~~~						1111111	<i>millititi</i>
		//////////////////////////////////////			DF, RT, GR, etc.)		12. County	
	7777.		<u>6819.6</u>	ft. G	.L.		Rio Arril	oa ////////////////////////////////////
16.	Che	ck Appropriat	e Box To Inc	licate N	ature of Notice, R	eport or Otl	ner Data	
NOTI		F INTENTION					REPORT C	)F:
PERFORM REMEDIAL WORK	7		PLUG AND ABA			(E)		
F	╡		FEGG AND ABA		REMEDIAL WORK			TERING CASING
TEMPORARILY ABANDON	-		CHANGE BLANCE		COMMENCE DRILLING OP	<del> </del>	PLI	US AND ABANDONMENT
PULL OR ALTER CASING			CHANGE PLANS		CASING TEST AND CEMEN	8.0 L 19		
					OTHER		<del></del>	L
OTHER								
17. Describe Proposed or C	omplete	d Operations (Cla	arly state all per	tinent deta	ils, and give pertinent d	lates, including	estimated date	of starting any proposed
work) SEE RULE 1103.					,			,
May 5, 1977 - Mo	oved ubing	in rig up	Big "A" We	11 Ser	vice; pull rods	s, pressui	e test tu	ibing, pull
1077 5		• . •						
May 6, 1977 - Ru	un ir	n with stra	ddle-packe	r set	up. Isolated (	Gallup per	forations	; 5774-96 ft.
K	B. I	Pumped 12 b	bls. of MR	-l aci	d with 22.5 bb1	ls. oil fl	lush. Tre	eated at 1000 PS
St	wabbe	ed back 3/	bbls. oil.	Move	d packers to Me	esa Verde.	Treated	l with 6 bbls.
M	R-1 a	acid and 18	bbls. flu	sh.	Well on vacuum.	. Trip-ou	it with pa	ickers.
Si	hut d	lown over n	ight.			-	-	
May 7, 1977 - Ra	an tu	ıbing; swab Rig down	bed 25 bbl	s. oil	, spent acid.	Ran rods	& pump ar	nd put on to
P	r ·	0 20#11					-	
							REN S	
		•		-				
							Š.	
						1 King to	**	\
						64.00	*	1
18. I hereby certify that the	informa	ation above is the	e and complete to	the best	f my knowledge and heli	ler.\	<del>; , , , , , , , , , , , , , , , , , , ,</del>	<del> </del>
		-1 //		•	· · · · · · · · · · · · · · · · · · ·	JOHN !	-32 1	
office		1 1/10	•		Fnain	<b>\</b>		for 16 1077
SIGNED WAY	2	· were		TTLE	Engineer		DATE	lay 16, 1977
7								
Original Signed	by A.	R. Kendri	<b>∘</b> }•		_			·
APPROVED BY		1131.01 1(	<u>∕₽</u> T	ITLE	I THE TRUE AND AND A	<u> </u>	DATE	
CONDITIONS OF APPROV	AL, IF	ANYI			•		•	