

well file

OFF. 325-5093
RES. 327-9094

J. GREGORY MERRION
PETROLEUM ENGINEER
P. O. BOX 507
FARMINGTON, NEW MEXICO 87401

May 6, 1976

New Mexico Oil Conservation Commission
1000 Rio Brazos
Aztec, New Mexico 87410

ATTENTION: Mr. A. L. Kendrick
District Supervisor


Gentlemen:

Enclosed please find Form C-103 to plug and abandon the Pictured Cliffs side of my Edna #4 dual completion. This well has not been able to produce into the line since a workover in November, 1974.

In view of the fact that I intend to continue to produce the deep side of this well, at this time I have not provided any other plugs other than the squeezing of the Pictured Cliffs. However, if you think it advisable, please let me know.


In view of the fact that the well was not capable of production during 1975, the scheduled packer leakage test was not run and we request that you waive the requirement since the well is scheduled for plugging.

Yours very truly,


J. Gregory Merrion

JGM/eh

Enclosure






OIL CONSERVATION COMMISSION

STATE OF NEW MEXICO
1000 RIO BRAZOS RD. - AZTEC

87410

LAND COMMISSIONER
PHIL R. LUCERO



STATE GEOLOGIST
EMERY C. ARNOLD

DIRECTOR
JOE D. RAMEY

April 19, 1976

J. Gregory Merrion
P. O. Box 507
Farmington, New Mexico

Re: Edna #4, H-7-24N-6W

Gentlemen:

The packer-leakage test for the above captioned well has not been received for the year 1975 as per rule 112-A 6 C.

If a packer leakage test on this well is not received within thirty days, the transporters will be ordered to cease taking products.

The shut-in order will remain in effect until further order of the Commission.

If there are questions, please contact this office.

Yours very truly,

N. E. Maxwell, Jr.
Engineer, District #3

NEM:mc

cc: Oil Conservation Commission
Santa Fe, New Mexico

LETTER FROM MERRION
PLAN TO PYA P.C. SIDE
NO TEST REQUIRED