



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. SP 684420
Unit Mexico Fed #7

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 27, 19 60

Mexico Fed #7

Well No. 1 is located 1450 ft. from N line and 990 ft. from W line of sec. 9

NE 1/4 Sect. 9 24E 1W NMPS
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Wilcox - FC Rio Arriba New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

It is our intention to plug and abandon well No. 1. This well was drilled to a depth of 3610' and no production was found of commercial value. Our program for plugging is as follows:

Squeeze offsetting perforations 3564-80' and 3584-90' with 35 sacks regular cement. Run free point indicator to find where casing is free. Cut casing and set 100' cement plug above set. After pulling casing, set 15 sack cement plug in top of 8-5/8" OD surface casing.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations are commenced.

Company Shelly Oil Company

Address Dr. 510

Farmington, New Mexico

By (Signed) P. E. Cosper

Title District Superintendent

