

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-039-05601
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. N/A
7. Lease Name or Unit Agreement Name E. J. Hooten
8. Well No. #1
9. Pool name or Wildcat Blanco Pictured Cliffs
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator EOG (New Mexico) Inc.	3. Address of Operator 621 17th St., Suite 1800, Denver, CO. 80293	4. Well Location Unit Letter D : 990 Feet From The FNL Line and 990 Feet From The FWL Line 12 Section 24N Township 1W Range NMPM Rio Arriba County
--	---	--	--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: MIT Test <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) EPNG Locate Gas Lines
- 2) Set 4 Anchors
- 3) MIRU PU
- 4) POH 1" Tbg. LD on Float
- 5) Notify NMOCC to witness
- 6) RIH 2-3/8" Workstring & 4-1/2" Mod "R" packer
- 7) Set packer
- 8) Press test 4-1/2" x 2-3/8" annulus to NMOCC specs
- 9) POH 2-3/8" tbg & packer. LD on Float
- 10) NU valve on casing
- 11) SI well. If needs repair, will repair later.

RECEIVED
MAY - 9 1994
OIL CON. DIV.
DIST. 8

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Conni Smith TITLE Sr. Engineering Tech. DATE 5/6/94
TYPE OR PRINT NAME Conni Smith TELEPHONE NO. _____

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY ERNIE BUSCH DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE MAY 13 1994

CONDITIONS OF APPROVAL, IF ANY: