

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER		5. LEASE DESIGNATION AND SERIAL NO. Jicarilla 09-000013
2. NAME OF OPERATOR Ken Blackford		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Apache Tribe
3. ADDRESS OF OPERATOR P. O. Box 108, Lubbock, Texas 79408		7. UNIT AGREEMENT NAME - - - - -
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Well 13 #2 NE SW Section 23, T-24-N, R-5-W, Rio Arriba County, New Mexico		8. FARM OR LEASE NAME Jicarilla Apache
14. PERMIT NO. Tract 21		9. WELL NO. 13 #2
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6,681' DF		10. FIELD AND POOL, OR WILDCAT Otero FC
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 23, T-24-N, R-5-W, N. M. P. M.
		12. COUNTY OR PARISH Rio Arriba
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) Remedial Work	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

August 18th: Move in Aztec Well Service Cardwell Unit No. 34 from Well 37P #1. Bleed pressure off. Remove wellhead.

August 19th: Pulling 78 joints 2" tubing. Running rabbit through tubing. Running sand pump. Shut well in.

August 20th & 21st: Operation shut down.

August 22nd: Bleed off pressure. Running sand pump. Shut well in.

August 23rd: Bleed off pressure. Running sand pump. Running 78 joints 2" tubing. Land tubing. Swabbing tubing. Hooked up well and placed on production. Released Aztec Unit.

RECEIVED

SEP 15 1977

U. S. GEOLOGICAL SURVEY
LUBBOCK, TEXAS

18. I hereby certify that the foregoing is true and correct

SIGNED Ken Blackford

TITLE Operator

DATE September 14, 1977


(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

*See Instructions on Reverse Side



Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.