

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐

2. NAME OF OPERATOR
Getty Oil Company

3. ADDRESS OF OPERATOR
P.O. Box 3360, Casper, WY 82602

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980' FSL & 1980' FEL
AT TOP PROD. INTERVAL: Same
AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>		<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>		<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>		<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>		<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>		<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>		<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>		<input checked="" type="checkbox"/>
(other)			

5. LEASE
Contract #68

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Jicarilla Apache

7. UNIT AGREEMENT NAME
--

8. FARM OR LEASE NAME
Jicarilla "B"

9. WELL NO.
7

10. FIELD OR WILDCAT NAME
Otero Gallup

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
J Section 32 - T25N - R5W

12. COUNTY OR PARISH
Rio Arriba

13. STATE
New Mexico

14. API NO.
--

15. ELEVATIONS (SHOW DF, KDB, AND WD)
6662' DF 6653' GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

OIL CON. DIST. 3

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well was plugged and abandoned on 8/24/81. Cement plugs were set as follows:

Spotted 75 sx. cement from 6090'-5830'.
Perforated w/2, .40" holes 4776'-4777' and pumped 35 sx of Class "B" Neat cement into perfs (cement from 4776'-4670').
Perforated w/ 2 SPF 4174'-4074'. Pump 40 sx Class "B" Neat cement into perfs (4174'-4070' inside and outside casing).
Spotted 20 sx. cement from 2635' to 2535'.
Spotted 20 sx. cement from 2260' to 2160'.
Perforated w/ 2 SPF 1805'-1705'. Cemented w/ 50 sx Class "B" cement.
Perforated w/ 2 SPF 409'-309'. Cemented w/ 40 sx. Class "B" cement.
Cut off 5 1/2" casing @ 278' (recovered 278' of 5 1/2" casing).
Set 50 sx. plug from 120' to surface. Set dry hole marker.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Dw. Banner TITLE Area Superintendent DATE 9/6/81

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: