UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL

PULL OR ALTER CASING

MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)

Form 9-331 Dec. 1973	- CNorm Joseph Com 1424		
UNITED STATES	5. LEASE		
DEPARTMENT OF THE INTERIOR	Contract No. 34		
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME		
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)			
reservoir, Use Form 9-331-C for Such proposars.)	8. FARM OR LEASE NAME		
1. oil gas other	Jicarilla "C"		
	9. WELL NO.		
2. NAME OF OPERATOR	10. FIELD OR WILDCAT NAME		
Getty Oil Company 3. ADDRESS OF OPERATOR			
P. O. Box 3360, Casper, Wyoming 82602	Otero Gallup 11. SEC., T., R., M., OR BLK. AND SURVEY OR		
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	AREA Sec. 33-T25N-R5W		
AT SURFACE: 1980' FNL & 660' FEL	12. COUNTY OR PARISH 13. STATE		
AT TOP PROD. INTERVAL:	Rio Arriba N.M.		
AT TOTAL DEPTH:	14. API NO.		
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,			
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6783'GR 6793'DF		
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF			
FRACTURE TREAT USAGE SHOOT OR ACIDIZE	a Paga		

(NOTE: Report results of m

change on Form 9

JJCK 2-C-81

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Decision to P & A made as a result of finding holes in csg from 958' up to 260' Verbal approval to P & A was obtained from Mr. Errol Becher of U.S.G.S in Farmington in phone conversation with Mr. T. I. Marsh at 1:30 P.M., 10/6/80 Mr. Becher advised us to spot 3-25 sk plugs, one each @ 3760', 2820' and 2220'. and to set cmt plug from 958' to surface, inside and outside of 5 ½' csg. were to be in addition to plugs outlined in previous Sundry Notice for Plug back and hold. (See Attached)

Subsurface Safety Valve: Manu, and Typ	e		Set @	Ft
18. I hereby certify that the foregoing is	true and correct	rintenden (DATE]	/20/81	
	(This space for Federal or S	tate office use)		
APPROVED BY	TITLE	DATE	-501	/ED

*See Instructions on Reverse Side

APPROVED

DISTRICT OIL & GAS SUPERVISOR

Attachment to Notice of Intention to Abandon

9. S. GEOLOGICAL SURVEY P. O. Box 959 Farmington, New Mexico 87401

Re: Permanent Abandonment

Well 22) icarilla

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases".
- 2. The Farmington office (telephone (505) 325-4572) is to be notified in sufficient time for a representative to witness all plugging operations.
- 3. Blowout prevention equipment is required.
- 4. In addition to normal filling of pits and cleanuprof location, additional surface restoration work may be required, i.e. ripping of pad and/or access road/ reseading, etc. We have asked the Bureau of Land Managarunt for the surface restoration requirements for this well and we should be able to furnish you these requirements within 30 days. After plugging the well and before making final clean-up, you should contact this office unless you have already been advised as to what additional surface restoration work is required.
- 5. The surface management agency is to be notified when surface rehabilitation is complete.
- 6. The following modifications to your plugging program are to be made (when applicable):

Office Hours: 8:00 A.M. to 5:00 P.M. Farmington Personnel to be notified:

Home Telephones:

Ray Swanson: Petroleum Engineering Technician - 325-8189
Fred Edwards: Petroleum Engineering Technician - 325-7885
Ken Baker: Petroleum Engineering Technician - 327-2170