Form 9-331 May 1963)

UNITED STATES SUBMIT IN TRIPLICATE* (Other justructions on re-

	Form approved Budget Bureau	Ŋ,
LEASE	DESIGNATION	

em approved idget Bureau	No	42	R1424
CONTROL AND LAND			MA

	GEOLOGICAL SURVE	V	1 .	TO DODECE
	OTICES AND REPOR	TS ON WELLS	6.	SF-080565A if indian, allotted
Use "APP	LICATION FOR PERMIT " for a	such proposals.)		UNIT AGREEMENT A
WELL WELL XX OTHE	C.R.		8.	FARM OR DEADE SAN.
Gulf Oil Corporation				Stevie Joe
	Mexico 88240			4
Box 670, Hobbs, New Location of Well (Report locations of Seconds) At surface	ion clearly and in accordance wit	h any State requirements.*		FIELD AND POOL, OR W
1850' RSL & 790' FEL,	Section 6, 25-N, 3	−W	11.	SURVEY OR AREA
4. PERMIT NO.	15. ELEVATIONS (Show whether	ther DF, RT, GR, etc.)	12	Sec 6, 25-N, 3-c
	7.	313' GL		Rio Arriba New
6. Check	Appropriate Box To Indice	ate Nature of Notice,	Report, or Othe	r Data
NOTICE OF I	NTENTION TO:	1	SUBSEQUENT	REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-	OFF	REPAIRING WELI
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TE	i—-	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR	losed in Re	ABANDONMENT*
(Other)	CHANGE PLANS	(Note:	Report results of n	nultiple completion on Wei. Report and Log form
nent to this work.)* ect well uneconomical		e locations and measured s	ind true vertical de	uding estimated date of start of pths for all markers and zone
nent to this work.)* ect well uneconomical		e locations and measured s	ind true vertical de	pins for an markers and zone
nent to this work.)* ect well uneconomical		time. To be ca	ind true vertical de	pins for an markers and zone
nent to this work.)* ect well uneconomical	to produce at this	time. To be ca	ind true vertical de	pins for an markers and zones.
nent to this work.)* ect well uneconomical	to produce at this	time. To be ca	ind true vertical de	pins for an markers and zones.
nent to this work.)* ect well uneconomical	to produce at this	time. To be ca	arried as cl	pins for an markers and zones.
nent to this work.)* ect well uneconomical	to produce at this	time. To be ca	ind true vertical de	pins for an markers and zones.
ect well uneconomical ther well study.	to produce at this	time. To be ca	arried as cl	pins for an markers and zones.
nent to this work.)* ect well uneconomical	to produce at this	time. To be ca	arried as cl	pins for an markers and zones.
ect well uneconomical her well study.	to produce at this	time. To be ca	arried as cl	pins for an markers and zones.
ect well uneconomical her well study.	to produce at this	time. To be ca	rried as cl	pins for an markers and zones.
ect well uneconomical her well study.	ing is true and correct	time. To be ca	rried as cl	osed in, pending