Robert L. Bayless

PETROLEUM CLUB PLAZA BUILDING
P. O. BOX 1541
FARMINGTON, NEW MEXICO 87401

June 10, 1975

Ash.

New Mexico Oil Conservation Commission P.O. Box 2088 Santa Fe, New Mexico 87501

ATTENTION: Mr. James Kapteina

Re: Canada Mesa #5

Gentlemen:

We previously asked and received a non-standard location for this well under your order NSL-712. This was applied for after the archaeologist had approved the location. Now the Bureau of Land Management feels it is too close to the abandoned ranch house ruins so we request the attached location which moves the well approximately 100 feet further away from the ruins.

We hope you will be able to approve this administratively to expedite our drilling program.

Yours truly,

MERRION & BAYLESS

ROBERT L. BAY

RLB/su

CC New Mexico Oil Conservation Commission Aztec, New Mexico



NEW MEXICO OIL CONSERVATION COMMISSION WELL LOCATION AND ACREAGE DEDICATION PLAT

Form C-102 Supersedes C-128 Effective 1-1-65

All distances must be from the outer boundaries of the Section. Well No. Lease Operator Canada Mesa Merrion & Bayless Range County Township Unit Letter Section 6w Rio Arriba 2և N n Actual Footage Location of Well: 970 line feet from the North line and Dedicated Acreage: Producing Formation Ground Level Elev. -80 Devils Fork Acres Gallup 6486 1. Outline the acreage dedicated to the subject well by colored pencil or hachure marks on the plat below. 2. If more than one lease is dedicated to the well, outline each and identify the ownership thereof (both as to working interest and royalty). 3. If more than one lease of different ownership is dedicated to the well, have the interests of all dated by communitization, unitization, force-pooling. etc? If answer is "yes," type of consolidation If answer is "no," list the owners and tract descriptions which have actually been consolidated. (1) this form if necessary.) No allowable will be assigned to the well until all interests have been consolidated (by communitization) forced-pooling, or otherwise) or until a non-standard unit, eliminating such interests, has been approved by CERTIFICATION I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief. 9701 Name Position Company Merrion & Bayless June_10, 1975 Sec 10 I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my knowledge and belief. Date Surveyed April 16, 1975 Registered Professional Engineer Certificate No. 3950 500 1000

2000

1320 1650

660

1980 2310

1500

April 21, 1975



New Mexico Oil Conservation Commission P.O. Box 2088 Santa Fe, New Mexico 87501

Re: Unorthodox location of our Canada Mesa #5.

Gentlemen:

Enclosed please find a survey plat showing our proposed location for the above referred to Gallup test well. Along with the plat is a topographic map showing the problems involved in drilling this on our desired site of 990 feet from the north and west lines. However, you will note we have moved the location as described in the survey plat. This is because of the extremely steep rock bluff outcrop on a line to the north and west of the location and in addition there is a rock adobe ranch house ruin which exists next to the 990 location. The archaeologist, on examing the site, extimated that the house was over 50 years old and thus comes under the antiquities act and must not be disturbed.

We are sending a copy of this letter to the other operator who lies within a mile of the location. The acreage holder immediately south of this location is J. Cregory Merrion, et al; we are the operators of the acreage to the north, northwest and west of the location. We would like to commence this well at the earliest possible date; therefore, please advise if we can do anything to expedite your approval of this location.

Yours truly,

MERRION & BAYLESS

Ву		\
ROBERT	L.	BAYLESS

RLB/su
Enclosures
cc NMOCC - Aztec
M & M Production
Lindrith, New Mexico