

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF-080107

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Shawnee

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Lybrook Gallup

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 33-T24N-R7W

12. COUNTY OR PARISH 13. STATE

Rio Arriba New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.

1. ☒ OIL ☒ GAS ☐ WELL ☐ OTHER

2. NAME OF OPERATOR
BASIN FUELS, INC.

3. ADDRESS OF OPERATOR
152 Petroleum Center Bldg., Farmington, NM 87401

4. LOCATION OF WELL - Report location clearly and in accordance with any State requirements.
See also space 17 below.
At surface:
485' FSL & 1945' FEL

14. DEPTH OF NO. 15. ELEVATIONS (Show whether DE, RT, GR, etc.)
7387 K.B.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

Intention to Drill.

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROGRESS OF COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

11-7-74: Run correlation collar log. Perf. Gallup sand 5959-65 & 5068-72 w/4 jets/ft.

11-8-74: Ran packer on 2 3/8" tbg. & acidize perfs. w/1000 gal. 15% MCA.

11-9-74: Swab load. Pull tbg. & packer.

11-11-74: Frac Gallup perfs. w/18,000 gal. oil foam & 17,000 # 20-40 sd. Frac. screened out. Hook up test lines & start clean out.

11-12-74: Run tbg. Testing.

11-30-74: Set pumping unit - run rods & insert pump. Testing.

1-8-75: Testing - Evaluating opening additional zones & refracing well.

18. I hereby certify that the foregoing is true and correct

SIGNED

Jack D. Cook

TITLE

Engineer

DATE 1-9-75

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

JAN 9 1975

*See Instructions on Reverse Side