1200 SECURITY LIFE BUILDING DENVER, COLORADO 80202



TELEPHONE 303 - 629-1050

January 23, 1976

Lynco Oil Corporation #2 Denver Tech. Center 7890 E. Prentice Englewood, CO 80110

Re: Regina #6-Hole Deviation B, 34-24-7

Gentlemen:

The following deviation tests were taken during the drilling of the subject well:

Depth	Deviation	
65 '	1/2	degree
510	1/2	11
1110	1	11
1580	1	11
2030	1	11
2576	1/2	**
3021	1/2	11

Total Depth 3050'

Very truly yours,

SIGNAL OILFIELD SERVICE, INC.

L. F. Stone President

State of Colorado
) ss.

County of Denver
)

Sworn to before me this
23rd day of January , 1976.

Notary Public

(151-5-9-1976 OH, 10-1-7

My Commission Equipme For 20,1007