Form 9-331 (May 1963)

APPROVED BY _

CONDITIONS OF APPROVAL, IF ANY:

UNITED STATES

SUBMIT IN TRIPLICATE*

Other Instructions on reverse side

Form approved,
Budget Bureau No. 42 R1424.

LEASE DESIGNATION AND SERIAL SO.

Jicarilla Apache Tribal

DATE ___

GEOLOGICAL SURVEY	Contract. #123
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or pla; and k to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)	6. If Indian, Allotter on tribe name Jicarilla Apache
L. OH. CAS GAS WELL X OTHER	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	S. FARM OR LEASE NAME
Northwest Production Corp. 3. ADDRESS OF OPERATOR	Jicarilla 125 C
P. O. Box 990, Farmington, New Mexico 87401 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface	10. FIELD AND POOL, OR WILDOAT
1500' N, 1600' W	So. Blanco Pictured Cliffs 11. SEC., T., R., M., OR BLK. AND SURVEY OR ABEA Sec. 8, T-25-N, R-4-W NMPM
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 7.339 GL	12. COUNTY OR PARISH 13. STATE Rio Arriba New Mexico
16. Check Appropriate Box To Indicate Nature of Notice, Report, or C	
NOTICE OF INTENTION TO: SUBSEQU	ENT REPORT OF:
	REPAIRING WELL, ALTERING CASING ABANDONMENT* of multiple completion on Well letion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, proposed work.)* O4-27-77 T.D. of 3874'. Ran 128 joints 2 7/8", 6.4#, J-55 proposed at 3874'. Baffle set at 3863'. Cemented with 1 l8 hours. Top of cement at 2900'.	oduction casing, 3862'
05-27-77 Tested casing to 4000# - ok. PBTD 3863'. Perfed 3752', 3810', 3812', 3818', 3823 zone. Frac'd with 20,000#10/20 sand and 20,000 ga Dropped no sets of balls. Flushed with 924 gallons	allons treated water.
	· · · · · · · · · · · · · · · · · · ·
	U. 0
18. I hereby certify that the foregoing is true and correct SIGNED	June 1, 1977

TITLE _