UNITED STATES S DEPARTMENT OF THE INTERIOR \$

SUBMIT IN TRIPLICATE*
(Other instructions on re-

Form approved, Budget Bureau No. 42-R1424 LEASE DESIGNATION AND SERIAL NO.

| | DEPARTMENT OF THE INTERIOR VERS | e side) | 5. LEANE DESIGNATION AND SERIAL NO. |
|--|--|--|--|
| (Do not use this for U | TY NOTICES AND REPORTS ON WE for proposals to drill or to deepen or plug back to a deepen or plu | | Contract No. 26 6. D INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Apache |
| OIL X GAS WELL X | OTHER | | 7. UNIT AGREEMENT NAME |
| 2. NAME OF OPERATOR | | | 8. FARM OR LEASE NAME |
| Cotton Petrol | eum Corporation Att: Mr. | Frank Hiesta | and Apache |
| 3. ADDRESS OF OPERATOR] | .660 Lincoln Street | | 9. WELL NO. |
| 2502 Lincoln | Cneter Building Denver, Col | Lorado 80264 irements.* | 106 10. FIELD AND FOOL, OR WILDCAT Lindrith Gallup- Dakota West |
| 2040'FNI | , 945'FEL | | Dakota West 11. SEC., T., E., M., OB BLE. AND SURVEY OF AEDA Sec. 1-T24N-R4W |
| 14. PERMIT NO. | 15. ELEVATIONS (Show whether DF, RT, GR, etc. 7008 'GL, 7019 'DF, 702 | | N.M.P.M. 12. COUNTY OR PARISH 13. STATE Rio Arriba NM |
| 16. | Check Appropriate Box To Indicate Nature of | Notice, Report, or C | Other Data |
| NOT | CE OF INTENTION TO: | | DENT REPORT OF: |
| TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) | MULTIPLE COMPLETE FRA ABANDON* CHANGE PLANS (Of | Completion or Recompl | of multiple completion on Well etion Report and Log form.) |
| DESCRIBE PROPOSED OR CO proposed work. If we nent to this work.) * | MPLETED OPERATIONS (Clearly state all pertinent details, a li is directionally drilled, give subsurface locations and n | and give pertinent dates, neasured and true vertica | including estimated date of starting any all depths for all markers and zones perti- |
| 1-09-78 | Spud well. | | |
| 1-09-78 | T.D. 352'. Ran 8 jts., 8 5/ (323') set at 335' with 30 3% CaCl and ½lb. Flocele per Pressure test with 500 psign. T.D. 7860'. Ran 239 jts., S<&C, K-55 casing (7825') FIRST STAGE: 500 sacks 50/ and 6½ lbs Gilsonite per sack cement at 6000'. SECOND STAGE: 400 sacks 65 6½ lbs. Gilsonite per sack "B" neat cement. Calculate Stage cementing tool at 448 | o sacks Claser sack. Cem Test OK. 4½", 10.50 & set at 7836 50 Formix with the Calcula 735 Pormix (followed by d top of cem | s "B" Cement with ent circulated. 11.60 lbs., ' with: th 6 lbs salt ted top of 12% gel) with 50 sacks Class |
| 18. I hereby certify that the | | Walsh Engine | Section of the second section in the second section is a second section in the second section in the second section is a section in the section in the section in the section is a section in the section in the section in the section is a section in the section in |
| SIGNE | N. Walsh, P.E. | ction Corp. | DATE February 3, 1978 |
| (This space for Federal | or State office use) | | in the second of |

APPROVED BY ______CONDITIONS OF APPROVAL, IF ANY: