

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <i>30-039-21589</i>
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐ <i>APR 23 1989</i>	7. Lease Name or Unit Agreement Name <i>Jicarilla 30</i>
2. Name of Operator <i>Conoco Inc.</i>	8. Well No. <i>7</i>
3. Address of Operator <i>P. O. Box 460 - Hobbs, NM 88240</i>	9. Pool name or Wildcat <i>Lindiith Calley Dakota, W</i>
4. Well Location Unit Letter <i>0</i> : <i>800</i> Feet From The <i>south</i> Line and <i>1650</i> Feet From The <i>east</i> Line Section <i>30</i> Township <i>25N</i> Range <i>4W</i> NMPM <i>San Arriba</i> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: <i>Recomplete & Dual</i> ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work started 8/8/88. Isolate Calley/Dakota w/ RBP at 6475'. Perf, acidize & frac. Point Lookout sand. Swab & test for 7 days, determine non-commercial. Squeeze off w/ cement. Re-set RBP at 5250'. Perf, acidize & frac. Cliffhouse sand. Swab & test for 5 days, determine non-commercial. Squeeze off w/ cement. Perf, acidize & frac. Chaco formation. Swab & test for 10 days, determine non-commercial. Squeeze off w/ cement. Retrieve RBP, return well to production. Well producing only in Lindiith Calley Dakota. Work completed 11/9/88.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *William W. Baker* TITLE *Administrative Supervisor* DATE *APR 23 1989*
TYPE OR PRINT NAME *WILLIAM W. BAKER* TELEPHONE NO. *(505) 397-580*

(This space for State Use)

Original Signed by FRANK T. CHAVEZ

APPROVED BY _____ TITLE _____ DATE *APR 23 1989*

CONDITIONS OF APPROVAL, IF ANY:

NMOC - Lyle (3) File