5. LEASE

Contract 127

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
deological solve:	Jicarilla Apache
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	1 (27 8 47)
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME TO LEASE Apache TERROR E SERVE
1. oil gas 1	9. WELL NO. 1966 - 2 5 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6
well 😾 well 🗆 other	124 (1.5 5 \$ \$ 6
2. NAME OF OPERATOR	10. FIELD OR WILDCAT NAME
Cotton Petroleum Corporation 3. ADDRESS OF OPERATOR	Lindrith Gallup- Dakota West
717 17th St., Suite 2200, Denver, Co. 80202	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA BEET OF BEET NO.
below.)	Sec. 4, T 24N, R 4W N.M.P.M. 12. COUNTY OR PARISH 13. STATE - 5
AT SURFACE: AT TOP PROD. INTERVAL: 660' FSL, 1980' FEL	■
AT TOTAL DEPTH:	Rio Arriba New Mexico 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	6753' GR 🕏 🗮 🖺 🗒 🛱 🗸 🗖
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	\$ 5 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
TEST WATER SHUT-OFF	
FRACTURE TREAT SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9-330.)
MULTIPLE COMPLETE	그 그 그 이 사용 원질 사회 하실 1 등 사회
ABANDON*	
(other)Move well location.	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*	
Deverisein is requested to mayo the	location of the Apache #124
Permission is requested to move the location of the Apache #124 Gallup Dakota oil well from 660' FSL, 1980' FEL, Sec. 4 to	
660' FEL, 1980' FSL, Sec. 4	
	등급화병원 기원 방설원을 다
This is required to maintain consistant spacing in Sec. 4, with	
the well being drilled in the NE% of a quarter section.	
the state of the s	
and the formal harmonic	
pental lecation	SEP 2 7 1979
	OIL CON Get @ Ft.
Subsurface Safety Valve: Manu. and Type	Dist. 3
18. I hereby certify that the oregoing is true and correct	
SIGNED D. E. WOOD WY away TITLE Division Prod. Mgr DATE September 21, 1979	
This space for Federal or State office use)	
Inis space for rederal of State of	An an all-
APPROVED BY TITLE	DATE L'ELVE
CONDITIONS OF APPROVAL, IF ANY:	
	SEP 2 6 1979