Form 9-331 (May 1963)	UNITED STATE PARTMENT OF THE	ES INTERIOR	SUBMIT IN TRIPLICA' (Other instructions on verse side)	5. LEASE	Form approved Budget Bureau DESIGNATION A	No. 42-R1424.	
/ /	GEOLOGICAL SU				ract No.		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)					G. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Apache 7. UNIT AGREEMENT NAME		
OIL GAS WELL	OTHER			Q FARM	OR LEASE NAMI	R	
2. NAME OF OPERATOR					Apache		
Cotton Petroleum Corporation 3. ADDRESS OF OPERATOR				l	9. WELL NO.		
717 17th Street, Suite 2200, Denver, Colorado 80202 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface					#116 10. FIELD AND FOOL, OR WILDCAT Lindrith Gallup- Dakota West 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA		
660' FNL & 1980' FWL					Sec. 12, T24N-R4W		
14. PERMIT NO.	15. ELEVATIONS (Sho	w whether DF, RT, (GR, etc.)	12. COUN	TY OR PARISH	13. STATE	
	6890' 6	GR		Rio_	Arriba	New Mexico	
16.	heck Appropriate Box To	Indicate Natur	e of Notice, Report,	or Other Dat	a		
	OF INTENTION TO:	-		BSEQUENT REPOR		<u></u>	
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COM proposed work. If well nent to this work.) *	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS PLETED OPERATIONS (Clearly statis directionally drilled, give su		WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (Note: Report re Completion or Re (ails, and give pertinent e and measured and true of	esults of multip	ort and Log Ioi	on Well	
1-13-79	Spud well.						
1-14-79	TD 384 '. Ran 9 275 sacks Class	jts of 8-9 B with 2% (5/8" 24#, K-55 c CaCl. Cement c	casing. : irculated	Set at 38 ·	34' KB with	
1-29-79	TD 7646'. Ran lat 7646' with:	41 jts of 4	1-1/2" 10.5# and	d 11.6#,	K-55 casi	ing. Set	
	Stage One:	600 sacks gilsonite	50/50 poz, 2% per sack.	gel, 6# sa	alt and 6	5-1/4#	
	Stage Iwo	110 sacks per sack.	65/35 poz with	10% gel,	12-1/2#	gilsonite	
		0 620 s acks	50/50 poz, 2%	gel. DV	tool at 4	1207'.	
18. I hereby certify that the	foregoing is true and correct	America Scale			0.14	2 70	
SIGNED	LUTTE	TITLE DIVIS	ion Production	manager r	OATE	7-17	
(This space for Federal	or State office use)				•		
APPROVED BYCONDITIONS OF APPR	OVAL, IF ANY:	TITLE		I	ATE		